



Ventures Auto Pte Ltd
1 Sin Ming Industrial Sector C
#01-117, Singapore 575 636
Reg: 202143430K
HP: 8323 6336

Not Authorized
1 Day @ 2500/-
Running After Repair
4 day

Vehicle Number : SLZ1286G
Vehicle Model : NISSAN PULSAR
Accident Date : 14.09.2024
Original Reg Date : 07.07.2017

Date : 16.09.2024
Chassis : VSKDDAC13U0098582
TP Ins. : SOMPO

ESTIMATE

S/n	Parts Description	QTY	Unit price	List Price	
1	REAR BUMPER <i>1228.70</i> <i>Bul/cm</i>	1	\$ 1,657.20	\$ 1,657.20	N ✓
2	REAR BUMPER INNER SIDE GARNISH	2	\$ 108.00	\$ <i>2</i> 216.00	N X
3	REAR BUMPER SIDE RETAINER <i>2</i>	2	\$ 95.20	\$ 190.40	N X
4	REAR BUMPER REINFORCEMENT	1	\$ 574.00	\$ <i>2</i> 574.00	N X
5	REAR BUMPER SPONGE <i>198</i>	1	\$ 268.00	\$ <i>cm</i> 268.00	N ✓
6	REAR FENDER INNER TRIMS <i>2</i>	2	\$ 685.00	\$ 1,370.00	N X
7	REAR FENDER INNER COWLING <i>2</i>	2	\$ 489.00	\$ 978.00	N X
8	TAIL LAMPS <i>2</i>	2	\$ 680.00	\$ 1,360.00	N X
9	TAILGATE	1	\$ <i>2</i> 4,487.30	\$ 4,487.30	N X
10	TAILGATE LOGO	1	\$ <i>2</i> 95.00	\$ 95.00	N ✓
12	TAILGATE LOCK DETECTOR	1	\$ <i>2</i> 198.00	\$ 198.00	N X
13	TAILGATE INNER LOCK	1	\$ <i>2</i> 235.00	\$ 235.00	N X
14	TAILGATE WEATHER STRIP	1	\$ 186.00	\$ <i>2</i> 186.00	N <i>502</i>
15	TAILGATE INNER TRIM BOARD	1	\$ <i>2</i> 602.00	\$ 602.00	N X
16	TAILGATE LOCK CATCHER	1	\$ <i>2</i> 163.00	\$ 163.00	N X
17	TAILGATE WINDSCREEN C/W MOULDING	1	\$ <i>2</i> 1,098.00	\$ 1,098.00	N X
18	REVERSE CAMERA	1	\$ <i>2</i> 750.00	\$ 750.00	N X
19	REAR END PANEL	1	\$ 843.30	\$ <i>2</i> 843.30	N X
20	REAR END PANEL TOP GARNISH	1	\$ 275.00	\$ <i>2</i> 275.00	N ✓
21	REAR EXHAUST PIPE	1	\$ <i>2</i> 1,107.90	\$ 1,107.90	N X
22	REAR EXHAUST INSULATOR	1	\$ <i>2</i> 230.00	\$ 230.00	N X
23	REAR EXHAUST MOUNTING	2	\$ <i>2</i> 25.00	\$ 50.00	N X

\$ 16,934.10

Less 10% \$ 1,693.41

\$ 15,240.69

C/F \$ 15,240.69



Ventures Auto Pte Ltd
1 Sin Ming Industrial Sector C
#01-117, Singapore 575 636
Reg: 202143430K
HP: 8323 6336

Vehicle No : SLZ1286G

B/F \$ 15,240.69

SPECIAL NETTS ITEM

S/n	Parts Description	QTY	Unit price	List Price	
24	Rear Number Plate W/Holder	1	\$ 120.00	\$ <i>Per</i> 120.00	SN X
25	Rear Bumper Clips	1	\$ 60.00	\$ <i>na</i> 60.00	SN X
26	Tailgate Windscreen Sealant	1	\$ 150.00	\$ <i>na</i> 150.00	SN X
27	TAILGATE WINDSCREEN INNER SEAL	1	\$ 120.00	\$ <i>na</i> 120.00	SN X
28	TAILGATE INNER TRIM BOARD CLIPS	1	\$ 60.00	\$ <i>na</i> 60.00	SN X
29	REAR BUMPER CARBON FIBRE STICKER (SPECIAL)	1	\$ 280.00	\$ <i>CM</i> 280.00	SN X
30	TAILLAMPS CLIPS (SET)	2	\$ <i>na</i> 50.00	\$ <i>na</i> 100.00	SN X
31	REAR FENDER INNER TRIM CLIPS (SET)	2	\$ 60.00	\$ <i>na</i> 120.00	SN X
32	REVERSE SENSOR	1	\$ 300.00	\$ <i>Per</i> 300.00	SN 200sn X
33	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 60.00	\$ <i>na</i> 60.00	SN X
34	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ <i>na</i> 150.00	SN X

\$ 1,520.00

LABOUR CHARGE

PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,500.00	400d
TO SPRAY PAINT AFFECTED AREA	\$ 1,500.00	400d
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00	20d
TO APPLY ANTI-RUST & TUFF KOTE	\$ <i>na</i> 150.00	X
REMOVE AND INSTALL REAR WINDSCREEN	\$ <i>na</i> 150.00	X
REMOVE, INSTALL AND CHECK REVERSE SENSOR FUCTION	\$ 150.00	50d
TO CONDUCT WATER LEAKAGE TEST	\$ <i>na</i> 150.00	X
TO TRANSFER TAILGATE PARTS	\$ <i>na</i> 120.00	X
TO REMOVE AND INSTALL REAR EXHAUST.	\$ <i>na</i> 150.00	X
Total :	\$ 20,780.69	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: