

# WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized repair sum \$10,600

Mr  
Mera-S

17 September 2024

18/9/24

P/P 10630.15

Take photo before painting

8 days.

REG NO. : SND 8201 Y  
MAKE/MODEL : MITSUBISHI ATTRAGE

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY | Nett<br>DESCRIPTION<br><del>EST</del> ITEMS | AMT(\$)                            |
|-----|---------------------------------------------|------------------------------------|
| 1   | Rear windscreen moulding                    | \$ 1pc 105.00 ✓                    |
| 1   | Rear boot lid                               | \$ body 991.00 ✓                   |
| 2   | Rear boot hinges                            | 282 n/s R \$ 1/5 trim 656.00 12c   |
| 1   | Rear boot lock                              | 197 \$ 1/5 trim 303.00 ✓           |
| 1   | Rear boot logo                              | 64 \$ 1pc 98.00 ✓                  |
| 1   | Rear boot outer chrome moulding             | 365 \$ 1pc 468.00 ✓                |
| 1   | Rear boot rubber                            | \$ 1pc 197.00 ✓                    |
| 1   | Rear boot "ATTRAGE" emblem                  | 22 \$ 1pc 65.00 ✓                  |
| 1   | Rear boot "C&C" emblem                      | \$ 1pc 50.00 X                     |
| 2   | Rear taillamps                              | \$ 1pc 1,418.00 ✓                  |
| 2   | Rear taillamp panels                        | 200 n/s R \$ 0/5 trim 400.00 12c   |
| 1   | Rear bumper                                 | \$ 1pc 785.00 ✓                    |
| 2   | Rear bumper brackets                        | \$ 1pc 130.00 X                    |
| 2   | Rear bumper reflectors                      | \$ 1pc 130.00 X                    |
| 2   | Rear bumper side retainers                  | 48.50 n/s R \$ 0/5 trim 97.00 12c  |
| 1   | Rear floor panel                            | \$ 1pc 955.00 X                    |
| 1   | Rear floor board                            | \$ 1pc 295.00 ✓                    |
| 1   | Rear floor mat                              | \$ 1pc 155.00 X                    |
| 1   | Rear chassis member                         | \$ 1pc 658.00 X                    |
| 1   | Rear exhaust silencer                       | \$ 1pc 758.00 X                    |
| 2   | Rear exhaust mountings                      | \$ 1pc 76.00 X                     |
| 1   | Rear end panel                              | 528 \$ 1pc 558.00 ✓                |
| 1   | Rear end panel inner garnish                | 98 \$ 1pc 145.00 ✓                 |
| 1   | Rear end panel air vent                     | \$ 1pc 52.00 X                     |
| 2   | Rear fenders                                | 895 n/s R \$ 0/5 trim 1,790.00 12c |
| 2   | Rear fender inner trims                     | 191 n/s R \$ 0/5 trim 382.00 12c   |
| 1   | Fuel pump assy                              | \$ 1pc 385.00 X                    |
| 1   | Rear boot spoiler                           | \$ 1pc 560.00 ✓                    |
| 1   | Rear boot "MIVEC" emblem                    | 50 \$ 1pc 88.00 ✓                  |
| 2   | Rear boot car plate lamps                   | \$ 1pc 182.00 ✓                    |
| 1   | Rear fender upper outer extension           | 260 \$ 1pc 325.00 ✓                |
|     |                                             | \$ 13,257.00                       |
|     | Less 10%                                    | \$ 1,325.70                        |
|     |                                             | \$ 11,931.30                       |

### SPECIAL NETT ITEMS

|   |                               |            |        |        |          |
|---|-------------------------------|------------|--------|--------|----------|
| 1 | Rear windscreen sealant       | \$         | Net    | 50.00  | 40 s/n   |
| 1 | Rear bumper clip (1 set)      | \$         | Net    | 50.00  | 30 s/n   |
| 1 | Rear number plate with holder | \$         | Net    | 50.00  | 40 s/n   |
| 1 | Rear reverse sensor (1 set)   | (K&V) \$   | Damage | 350.00 | X        |
| 1 | Rear reverse camera / set     | Damage/ \$ | Net    | 750.00 | 400 s/n  |
|   |                               |            |        | \$     | 1,250.00 |

S/N

### LABOUR CHARGES

|    |                                                              |    |          |      |
|----|--------------------------------------------------------------|----|----------|------|
| 1  | To remove, replaced damaged lamps and check up rear wiring.  | \$ | 80.00    | 20   |
| 2  | To remove and refit inner garnishes.                         | \$ | 150.00   | 60   |
| 3  | To remove and refit rear reverse sensor and camera.          | \$ | 150.00   | 30   |
| 4  | To transfer boot lid mechanism and wiring assembly.          | \$ | 80.00    | 50   |
| 5  | To remove and refit fuel tank assembly with all attachments. | \$ | 150.00   | X    |
| 6  | To remove and refit rear windscreen glass.                   | \$ | 180.00   | 120  |
| 7  | To remove, refit and replace exhaust silencer and mountings. | \$ | 150.00   | X    |
| 8  | To apply undercoating.                                       | \$ | 200.00   | 80   |
| 9  | Panel beating.                                               | \$ | 3,000.00 | 1500 |
| 10 | To re-spray painting on the affected areas.                  | \$ | 2,800.00 | 1300 |
|    |                                                              | \$ | 6,940.00 |      |

**GRAND TOTAL :**

**\$ 20,121.30**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

7- 7733-50  
102  
6960-15  
510  
3160  
10630-15