

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

18/9/24

17 September 2024

REG NO. : SND 8201 Y
MAKE/MODEL : MITSUBISHI ATTRAGE

P/P # 10630.15
Take photo before painting

8 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	Nett DESCRIPTION EST ITEMS	AMT(\$)
1	Rear windscreen moulding	\$ per 105.00 ✓
1	Rear boot lid	\$ body 991.00 ✓
2	Rear boot hinges	282 N/S R \$ 1/5 twi 656.00 12c
1	Rear boot lock	197 \$ but twi 303.00 ✓
1	Rear boot logo	64 \$ 100 98.00 ✓
1	Rear boot outer chrome moulding	365 \$ one 468.00 ✓
1	Rear boot rubber	\$ twi 197.00 ✓
1	Rear boot "ATTRAGE" emblem	22 \$ 100 65.00 ✓
1	Rear boot "C&C" emblem	\$ 50 50.00 X
2	Rear taillamps	\$ one 1,418.00 ✓
2	Rear taillamp panels	200 N/S R \$ 0/500 400.00 12c
1	Rear bumper	\$ 785 785.00 ✓
2	Rear bumper brackets	\$ 17 130.00 X
2	Rear bumper reflectors	\$ 17 130.00 X
2	Rear bumper side retainers	48.50 N/S R \$ 0/500 97.00 12c
1	Rear floor panel	\$ R 955.00 X
1	Rear floor board	\$ 295 295.00 ✓
1	Rear floor mat	\$ 17 155.00 X
1	Rear chassis member	\$ R 658.00 X
1	Rear exhaust silencer	\$ 17 758.00 X
2	Rear exhaust mountings	\$ 17 76.00 X
1	Rear end panel	528 \$ Body 558.00 ✓
1	Rear end panel inner garnish	98 \$ twi 145.00 ✓
1	Rear end panel air vent	\$ 52 52.00 X
2	Rear fenders	895 N/S R \$ 0/500 1,790.00 12c
2	Rear fender inner trims	191 N/S R \$ 0/500 382.00 12c
1	Fuel pump assy	\$ 17 385.00 X
1	Rear boot spoiler	\$ one 560.00 ✓
1	Rear boot "MIVEC" emblem	50 \$ 100 88.00 ✓
2	Rear boot car plate lamps	\$ one 182.00 ✓
1	Rear fender upper outer extension	260 \$ But 325.00 ✓
		\$ 13,257.00
	Less 10%	\$ 1,325.70
		\$ 11,931.30

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	All	50.00	40	S/W
1	Rear bumper clip (1 set)	\$	her	50.00	30	S/W
1	Rear number plate with holder	\$	Beat	50.00	40	S/W
1	Rear reverse sensor (1 set)	(Kov) \$	Dange	350.00	X	
1	Rear reverse camera / set	Dange/ \$	Che	750.00	400	S/W
		\$		1,250.00		

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		150.00	60
3	To remove and refit rear reverse sensor and camera.	\$		150.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$		80.00	50
5	To remove and refit fuel tank assembly with all attachments.	\$	11	150.00	X
6	To remove and refit rear windscreen glass.	\$		180.00	120
7	To remove, refit and replace exhaust silencer and mountings.	\$	11	150.00	X
8	To apply undercoating.	\$		200.00	80
9	Panel beating.	\$		3,000.00	1500
10	To re-spray painting on the affected areas.	\$		2,800.00	1300
		\$		6,940.00	

GRAND TOTAL :

\$ 20,121.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7- 7733.50
102
6960.15
510
3160
10630.15