

CARSMITH PRIVATE LIMITED

PREMIER@8 KAKI BUKIT AVE 4 #04-35 Singapore 415875

Tel: 9091 0000/ Email: claims@carsmith.biz

VEHICLE NO: SLE2978Y

MAKE & MODEL: HONDA SHUTTLE

DOA: 13.09.2024

CLAIM TYPE: TP CLAIM

Not Authorized
den
mcrans
18/9/24
d/s \$5100/
6 days
take phr Atk 12/20

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE 1193	1	\$ 1,864.00	DD Bent ✓
TAILGATE INNER TRIM BOARD	1	\$ 390.00	11 X
TAILGATE WEATHERSTRIP	1	\$ 197.00	11 X
TAILGATE INNER LOCK	1	\$ 286.00	11 X
TAILGATE DAMPER LH	1	\$ 231.00	11 X
TAILGATE DAMPER RH	1	\$ 231.00	11 X
TAILGATE LOGO	1	\$ 98.00	11 X
TAILGATE EMBLEM 'SHUTTLE' 80	1	\$ 95.00	11 X ✓
TAILGATE OUTER GARNISH	1	\$ 393.10	11 X
TAILGATE INNER HANDLE GARNISH	1	\$ 78.00	11 X
TAILGATE CHROME MOULDING GARNISH	1	\$ 268.00	Sub ✓
TAILGATE WIPER MOTOR	1	\$ 485.00	11 X
TAILGATE LAMP LH	1	\$ 358.00	11 X
TAILGATE LAMP RH	1	\$ 358.00	Bnd ✓
TAILLAMP RH 520.00	1	\$ 690.60	310 ✓
TAILLAMP PANEL RH	1	\$ 204.60	DD ✓
REAR QUARTER GLASS RH	1	\$ 576.30	11 X
REAR QUARTER GLASS WEATHERSTRIP RH	1	\$ 165.80	11 X
WINDSCREEN	1	\$ 1,230.00	11 X
WINDSCREEN MOULDING 110.20	1	\$ 256.00	11 X ✓
REAR END PANEL	1	\$ 910.00	12 X
REAR END PANEL TOP GARNISH	1	\$ 187.00	11 X
REAR BUMPER 936.00	1	\$ 1,530.00	Torn ✓
REAR BUMPER LOWER GARNISH	1	\$ 526.00	NF X
REAR BUMPER SIDE RETAINER LH	1	\$ 120.20	11 X
REAR BUMPER SIDE RETAINER RH 68.50	1	\$ 120.20	Gr ✓
REAR BUMPER BRACKET LH	1	\$ 98.00	NS X
REAR BUMPER BRACKET RH	1	\$ 98.00	NS X
REAR BUMPER SPONGE @ SGD 98	2	\$ 196.00	N/S n/s Torn pc
REAR BUMPER TOW COVER	1	\$ 48.00	7m ✓
REAR BUMPER REFLECTOR GARNISH RH 118.00	1	\$ 169.00	7m ✓
REAR BUMPER REFLECTOR RH 66.00	1	\$ 145.00	one ✓
REAR FENDER RH 1021.20	1	\$ 1,451.00	72/Bnd ✓
REAR FENDER INNER SHIELD RH	1	\$ 325.00	11 X
REAR FENDER INNER PANEL RH	1	\$ 2,234.00	12 X

\$ 16,612.80

LESS 20% \$ 3,322.56

SUB TOTAL \$ 13,290.24

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	nee 40 S/N

TAILGATE INNER SEAL	1	\$	50.00	11 X
TAILGATE SEALANT	1	\$	100.00	11 X
TAILGATE TRIMBOARD CLIPS	1 SET	\$	50.00	11 X
COATING	1	\$	600.00	11 X
REAR NUMBER PLATE	1	\$	80.00	11 X
REAR BUMPER CLIPS	1 SET	\$	50.00	11 405/n
REAR END PANEL SEALANT	1	\$	80.00	11 X
REAR END PANEL TOP GARNISH CLIPS	1 SET	\$	50.00	11 X
REVERSE SENSOR	1 SET	\$	480.00	11 X
REAR REVESE CAMERA	1	\$	450.00	11 X
SUB TOTAL		\$	2,090.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	20
TO REMOVE AND REFIT REAR TAILGATE GLASS TO FACILITATE THE REPAIR	1	\$ 200.00	120
TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	1	\$ 100.00	50
TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.	1	\$ 200.00	60
TO MEASURE, DRILLS HOLES ON ^{refit} REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	1	\$ 80.00	30
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,600.00	900
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,600.00	1000
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	50

SUB TOTAL \$ 3,980.00

GRAND TOTAL \$ 19,360.24

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts for reference
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5089.50
202
4071.60
80
2230
6381.6
202
5105