

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090318/AUA3Q2**Date:** 28/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700075030
Claimant Vehicle No : SNJ9057J **Insured Vehicle No :** SLT5558C
 Date of Loss: 03/09/2024 Nature of Claim: TP Claim No: 5905890208SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNJ9057J**
 Make & Model: MERCEDES-BENZ S400L, 3.0 R19 LED (A) Engine No: 27682430286609
 Reg. Date: 29/02/2016 (Man. Year: 2015) Chassis No: WDD2221652A219515
 Colour: White Odometer: 81827 km
 Engine Capacity: 2996 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R20 Rear Tyre Size: 275/35 R20
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,612.70	5,169.00	10,443.70	66.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,100.00	3,070.00	73.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,782.70	6,269.00	13,513.70	68.31
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	19,782.70	5,000.00	14,782.70	74.73
+ GST 9.00/9.00% (S\$)	1,780.44	450.00	1,330.44	74.73
Nett Amount (S\$)	21,563.14	5,450.00	16,113.14	74.73
+ Loss of Use (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		6,052.18		

INSPECTION

Date of Assignment: 16/09/2024
 Date Inspected: 16/09/2024 Inspected At: Success United Pte Ltd (HQ)
 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	4,570.00 FL	*3,560.00 FL
2	1		*REAR DOOR WEATHERSTRIP LH	Necessary	360.00 FL	*360.00 FL
3	1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	950.00 FL	*- FL
4	1		*SIDE ROCKER SKIRT LH	Repair	1,588.00 FL	*- FL
5	1		*SIDE SKIRT CHROME TRIM LH	Cracked	750.00 FL	*490.00 FL
6	1		*REAR WHEEL BEARING LH	Not Necessary	2,435.00 FL	*- FL
7	1		*REAR AMG SPORT RIM 20INCH LH	Cut	1,503.00 FS	*1,200.00 FS
8	1		*REAR AIRMATIC ABSORBER LH	Not Necessary	4,380.00 FL	*- FL
9	1		*REAR TYRE LH	Not Necessary	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,116.00	5,610.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,503.30	441.00
Total Parts (\$)	15,612.70	5,169.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR AND REPLACE DAMAGED BODYPARTS REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	300.00
2	TO REMOVE ,REPLACE REAR UNDERCARRIAGE PARTS	New	400.00	0.00
3	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	150.00	0.00
4	TO REMOVE,REPLACE REAR SPORTS RIM AND TYRE WITH BALANCING	New	120.00	40.00
5	WHEEL ALIGNMENT TEST	New	150.00	80.00
6	TO REMOVE ,REPLACE REAR DOOR ,TRANSFER GLASS ,GEAR SUCTION MOTOR AND DOOR TRIM ETC	New	350.00	80.00
7	TO PUTTY AND RESPRAY PAINTING ON REAR DOOR,REAR FENDER LH SIDE ROCKER SKIRT LH AND REAR BUMPER	New	1,500.00	600.00
Gross Labour Cost (\$\$)			4,170.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >