

# SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

Yan

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

## Estimate : TP24-109

Date : 13/09/2024

Vehicle Num. : SNJ9057J

Make/Model : Mercedes S400L-2015

Chassis/Eng# : WDD2221652A219515/27682430286609

Accident Date : 03/09/2024

Claim No. :

Reference :

Policy No. : SP2004883997 (07/03/2024)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Rear Door LH <i>Dented</i>		<del>4,570.00</del> <i>3560</i>
2.	1	Rear Door Weatherstrip LH <i>new</i>		<del>360.00</del>
3.	1	Rear Door Mechanism Lock LH <i>new</i>		<del>950.00</del> <i>+</i>
4.	1	Side Rocker Skirt LH <i>Reps new</i>		<del>1,588.00</del> <i>+</i>
5.	1	Side skirt chrome trim LH <i>could.</i>		<del>750.00</del> <i>+</i>
6.	1	Rear Wheel Bearing LH <i>new</i>		<del>2,435.00</del> <i>+</i>
7.	1	Rear AMG Sport rim 20inch LH <i>cut</i>		<del>1,670.00</del> <i>1200/SN</i>
8.	1	Rear Airmatic absorber LH <i>new</i>		<del>4,380.00</del> <i>+</i>
List TotalS\$ :				16,703.00
10.00% Discount S\$ :				1,670.30
				15,032.70
SPECIAL NETT ITEMS :				
1.	1	Rear Tyre LH <i>new</i>		580.00 <i>+</i>
Special Nett Total S\$ :				580.00
LABOUR :				
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				1,500.00 <i>3w</i>
To remove, replace rear undercarriage parts.				<del>400.00</del> <i>+</i>
To remove, rearrange electrical wirings, check lighting				150.00 <i>+</i>
To remove, replace rear sports rim and tyre with balancing.				<del>120.00</del> <i>40</i>

CONTINUE / ...

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29  
Kaki Bukit Autohub. Singapore 417921  
Tel No. : 67461515 / 67471787 Fax No. : 67485015  
Website : [www.successunited.com.sg](http://www.successunited.com.sg)  
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd  
AIG Building  
78 Shenton Way, #07-16  
Singapore 079120

Attention : Motor Claim Department  
Contact : 64191053 Fax No. : 68357416

Estimate : TP24-109

Date : 13/09/2024  
Vehicle Num. : SNJ9057J  
Make/Model : Mercedes S400L-2015  
Chassis/Eng# : WDD2221652A219515/27682430286609  
Accident Date : 03/09/2024  
Claim No. :  
Reference :  
Policy No. : SP2004883997 (07/03/2024)

S/N	Quantity	Particular	Unit Price	Amount S\$
		Wheel alightment test		<del>150.00</del> 80
		To remove, replace rear door, transfer glass, gear, suction motor and door trim etc.		<del>350.00</del> 20
		To putty and respray painting on rear door, rear fender LH, side rocker skirt LH and rear bumper.	1100	<del>1,500.00</del> 600
		Labour Total S\$ :		4,170.00
		<p>Adrian L 1/s 16/09/14 05 days</p> <p>total: <del>5069</del> \$6,269.00  1/s: <del>4050</del> \$5,015.20  \$5,000.00</p>		
		Total S\$ :		19,782.70

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Code: