

ASSIGNMENT

FRONT _____ Date: _____

Estim ^{Cost} _____

OD / TP RES / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W 0 km/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remarks: The vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNJ9057I Yr Regn: 2016, Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz 2000 2996

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 81827 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2221652A 215515

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/35R20

R: 275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 16/09/24

Survey held at: Success United

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG

COE Expiry

Estimate given during : Yes (✓)

1st Survey : No ()

MV :

PV :

Nett :

Date/Time, File Pass to?

☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Format:

Report Format: _____

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP24-109

Date : 13/09/2024

Vehicle Num. : SNJ9057J

Make/Model : Mercedes S400L-2015

Chassis/Eng# : WDD2221652A219515/27682430286609

Accident Date : 03/09/2024

Claim No. :

Reference :

Policy No. : SP2004883997 (07/03/2024)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Rear Door LH <i>Dented</i>		4,570.00
2.	1	Rear Door Weatherstrip LH <i>new</i>		360.00
3.	1	Rear Door Mechanism Lock LH <i>new</i>		950.00
4.	1	Side Rocker Skirt LH <i>new</i>		1,588.00
5.	1	Side skirt chrome trim LH <i>new</i>		750.00
6.	1	Rear Wheel Bearing LH <i>new</i>		2,435.00
7.	1	Rear AMG Sport rim 20inch LH <i>cut</i>		1,670.00
8.	1	Rear Airmatic absorber LH <i>new</i>		4,380.00
List TotalS\$:				16,703.00
10.00% Discount S\$:				1,670.30
				15,032.70
SPECIAL NETT ITEMS :				
1.	1	Rear Tyre LH <i>new</i>		580.00
Special Nett Total S\$:				580.00
LABOUR :				
To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident				1,500.00 <i>3w</i>
To remove, replace rear undercarriage parts.				400.00 <i>x</i>
To remove, rearrange electrical wirings, check lighting				150.00 <i>x</i>
To remove, replace rear sports rim and tyre with balancing.				120.00 <i>40</i>

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub, Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP24-109

Date : 13/09/2024
 Vehicle Num. : SNJ9057J
 Make/Model : Mercedes S400L-2015
 Chassis/Eng# : WDD2221652A219515/27682430286609
 Accident Date : 03/09/2024
 Claim No. :
 Reference :
 Policy No. : SP2004883997 (07/03/2024)

S/N	Quantity	Particular	Unit Price	Amount S\$
		Wheel alightment test		150.00 80
		To remove, replace rear door, transfer glass, gear, suction motor and door trim etc.		350.00 80
		To putty and respray painting on rear door, rear fender LH, side rocker skirt LH and rear bumper.		1,500.00 600
		Labour Total S\$:		4,170.00

Adrian
 1/s 16/09/24
 05 days

Total S\$: 19,782.70

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: