

國際汽車維修
KT MOTORWERK
Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 95287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No: 533734625

TO : **INCOME**
VEHICLE NO : **GBE1920M**
MODEL : **TOYOTA DYNA**
CHASSIS : **KDY2318018256**
DATE OF REG : **23.09.2015**
DATE OF ACCIDENT : **17.09.2024**

DATE : 20.09.2024

S/N	DESCRIPTION (REAR)	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,758.90	\$ 1,758.90
2	TAILGATE HINGE <i>2 pieces Bent</i>	4	\$ 223.50	\$ 894.00
3	TAILGATE SIDE LOCK <i>New</i>	2	\$ 184.90	\$ 369.80
4	TAILGATE STOPPER RUBBER <i>New</i>	2	\$ 62.00	\$ 124.00
5	TAILGATE STOPPER BRACKET <i>New</i>	2	\$ 165.00	\$ 330.00
6	REAR NUMBER PLATE HOLDER <i>Bent</i>	1	\$ 234.00	\$ 234.00
7	REAR NUMBER PLATE LAMP <i>New</i>	2	\$ 65.00	\$ 130.00
8	TAIL LAMP <i>Cracked</i>	2	\$ 387.00	\$ 774.00
9	TAIL LAMP SUPPORT BRACKET <i>Dented</i>	2	\$ 245.00	\$ 490.00
10	REFLECTOR LAMP <i>New</i>	2	\$ 55.60	\$ 111.20
11	REAR END PANEL <i>Dented</i>	1	\$ 1,689.60	\$ 1,689.60
12	REAR FLOOR PANEL <i>New</i>	1	\$ 2,867.00	\$ 2,867.00
13	SPARE BOX CARRIER <i>New</i>	1	\$ 673.50	\$ 673.50
14	SPARE TYRE CARRIER <i>New</i>	1	\$ 445.20	\$ 445.20
15	REAR EXHAUST <i>2</i>	1	\$ 768.20	\$ 768.20
16	REAR EXHAUST MOUNTING <i>mp</i>	2	\$ 76.00	\$ 152.00
17	REAR EXHAUST HOLDER <i>h</i>	1	\$ 170.00	\$ 170.00
18	REAR WIRE HARNESS	1	\$ 1,690.00	\$ 1,690.00

TOTAL PRICE \$ 13,671.40
LESS 25% \$ 3,417.85
SUB TOTAL PRICE \$ 10,253.55

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE '70KM/H' STICKER <i>3 New</i>	1	\$ 25.00	\$ 25.00
3	TAIL GATE '6 PAX' STICKER	1	\$ 25.00	\$ 25.00

TO : **INCOME**
 VEHICLE NO : **GBE1920M**
 MODEL : **TOYOTA DYNA**
 CHASSIS : **KDY2318018256**
 DATE OF REG : **23.09.2015**
 DATE OF ACCIDENT : **17.09.2024**

DATE : 20.09.2024

4	TAILGATE 1500kg STICKER <i>new</i>	1	\$ 60.00	\$ 60.00	<i>30</i>
5	TAILGATE DYNA STICKER <i>new</i>	1	\$ 68.00	\$ 68.00	<i>50</i>
6	TAILGATE ALUMINIUM PLATE (SPECIAL TYPE) <i>Best</i>	1	\$ 900.00	\$ 900.00	<i>500</i>
7	REAR CARRIER CANOPY (SET) <i>new</i>	1	\$ 2,200.00	\$ 2,200.00	<i>+</i>
8	REAR STOPPER <i>new</i>	2	\$ 55.00	\$ 110.00	<i>+</i>
9	REVERSE SENSORS (SET) <i>new</i>	1	\$ 250.00	\$ 250.00	<i>+</i>
10	REAR FLOOR PANEL TOP ALUMINIUM (SPECIAL TYPE) <i>new</i>	1	\$ 950.00	\$ 950.00	<i>+</i>
11	REAR END PANEL SEALANT <i>new</i>	1	\$ 200.00	\$ 200.00	<i>60</i>
12	REAR STEP BAR (SPECIAL TYPE) <i>Best</i>	1	\$ 550.00	\$ 550.00	<i>200</i>
			TOTAL	\$ 5,388.00	

900

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST AND REALIGN AFFECTED AREAS	\$ 1,200.00	<i>600</i>
2	TO PUTT AND SPRAY PAINT ON AFFECTED AREAS	\$ 1,200.00	<i>500</i>
3	REAR CHASSIS ALIGHMENT	\$ 200.00	<i>+</i>
4	REMOVE / INSTALL REAR REVERSE SENSOR	\$ 120.00	<i>+</i>
5	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 120.00	<i>+</i>
6	TO CONDUCT WIRING CHECK ON TAILLAMPS	\$ 120.00	<i>30</i>

1130

LKK Auto Consultants hence notify the Repairer of the following:
 TO CONDUCT WIRING CHECK ON TAILLAMPS

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be noted and is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer
 Signature:
 Date:

TOTAL \$ 2,960.00

total 4617.60

L/S: 3.7K

(3.7K)

Admin L
L/S 20/09/24
OSRays