

STYTECH AUTO PTE LTD

2 Kaki Bukit Ave 2 #01-03

Kaki Bukit Autohub Singapore 417921

Tel : 64448125 Fax : 64453310

GST Reg .No: 201601539K

Co.Reg: No: 201601539K

not Authorized
merch
18/5/24
2/5 \$4000
who phrs After reg
4 days

VEHICLE No: SLP 2112X

LIST ITEM

1PC	TAILGATE	DD/Bent	\$1,635.20
1PC	TAILGATE CX-3 EMBLEM	neu	\$58.50
1PC	TAILGATE REAR LOGO	neu	\$95.00
1PC	TAILGATE SKYACTIV EMBLEM	neu	\$58.00
1PC	TAILGATE WEATHERSTRIP	su	\$166.00 x
1PC	TAILGATE INNER LOCK	su	\$255.80 x
1PC	REAR BUMPER	DD	\$1,036.50
1PC	REAR BUMPER BEAM	Bent	\$345.50
1PC	REAR BUMPER SIDE RETAINER	11	\$48.00 x
1PC	REAR BUMPER LOWER	Dis (kur)	\$450.00 x
1PC	REAR END PANEL	DD/Bent	\$485.20
1PC	REAR END PANEL TOP GARNISH	11	\$182.90 x
			\$4,816.60
LESS 20%			\$3,853.28

S.NETT

1SET	REAR BUMPER CLIPS	neu	\$50.00 30
1PC	REAR END PANEL SEALANT	neu	\$50.00 ✓
1PC	REAR LICENCE PLATE	su	\$50.00 40
1PC	REAR WINDSCREEN SEALANT	neu	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	neu	\$50.00 20
1SET	REAR BUMPER REVERSE SENSOR	motor	\$280.00 200

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00 30
TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00 ✓
TO TRANSFER TAILGATE MECHANISM	\$60.00 ✓
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	\$60.00 ✓
TO SPRAY RUST PROOFING	\$60.00 ✓
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00 600
TO PUTTY & SPRAY PAINTING	\$1,500.00 750

TOTAL \$7,313.28

LKK Auto Consultants hence not

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 3713.90
202
2971.12
380
1700
5057.12
4240