

(08/11/13) Wef
ASS. REC. BY:

REF: CS/SMR24090325/Rnp3


3552

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SNQ 6673M
at Workshop m/s VANMAG
of ALEXANDER AN
Insured: SMR
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 165K
IDAC Accident Report: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNQ 6673M Yr Regn: 2024 / APR
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BYD ATTO 3 EXTENDED RANGE c.c. _____
Colour: GREY AC: Insured / Std / NI / NA
Sp. Reading: 11981 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: LXCE 4CB9 R2046269
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 235/50R18
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or CONTINENTAL

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>06/09/24</u>	D.O.I. <u>20/09/24</u>
Survey held at <u>ALEXANDER</u>	

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REDAM LIMIT - PK

We will be advising our principal a cost of repair P/P \$10,670.90 /- with 04 days of repair
(red, \$5267.9, 33%)

Date/Time, File Pass to?

☐
☐

Prel. Report

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

) S + RS \$ _____

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

305 Alexandra Road

159942 Singapore

Tel : 6376 8833

Fax : 6477 7398

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No. BY 6851	Date Estimated 10/09/2024	Page No. 1 of 2
Prepared By Clement Chia Cher-Yang		

ESTIMATE REPAIR FOR Kong Hai Lang 14 Choa Chu Kang Grove 1/3/1935 12:00:00AM Singapore 688209	ACCOUNT 14356 MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877
--	--

REGN. NO. SNQ6673M	CHASSIS NO. LGXCE4CB9R2046269	REGN. DATE 30/04/2024	MODEL ATTO 3 Ext Range	MILEAGE 8888
------------------------------	---	---------------------------------	----------------------------------	------------------------

DESCRIPTION

TO CONDUCT THIRD PARTY CLAIM AGAINST MS FIRST CAPITAL(SMB3607R).DOA:6/9/2024

REMOVE AND REPLACE REAR TAILGATE AND REAR BUMPER

REMOVE AND REPLACE REAR GLASS WITH WATER LEAK TEST

SUPPLY AND INSTALL 3M SOLAR FILM FOR REAR GLASS

PANEL BEAT REAR END PANEL WITH PAINT

SUPPLY AND INSTALL REAR NUMBER PLATE WITH FRAME

SPRAY PAINT REAR TAILGATE AND REAR BUMPER

TO CONDUCT BODY CAVITY PRESERVATION

TO CONDUCT ECU RE PROGRAMMING AND CLEAR OF ANY FAULT CODES TO ENSURE PROPER FUNCTION

SUNDRIES

VALUE

0.00

600 1,500.00

300 600.00

350.00

? 1,200.00

70.00

600 1,200.00

60 120.00

450 600.00

20 100.00

Total Labour 1:

5,740.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
13171273-00	WINDSCREEN ASSY - REAR <i>see photo</i>	1	1,200.00	10.00	1,080.00
13184244-00	MIDDLE TAIL LAMP <i>see</i>	1	1,457.00	10.00	1,311.30
13184243-00	LEFT REAR REFLEX REFLECTOR ?	1	21.00	10.00	18.90
12773367-00	LEFT LICENSE PLATE LAMP ?	1	45.00	10.00	40.50
11721028-00	FOG LAMP, REAR ?	1	132.00	10.00	118.80
14936137-00	BACK DOOR BYD LOGO ASSY <i>see</i>	1	90.00	10.00	81.00
14001538-00	BYD ATTO3 MARKER ASSEMBLY <i>see</i>	1	52.00	10.00	46.80
12957133-00	EV LOGO <i>see</i>	1	10.00	10.00	9.00
13182872-00	BACK DOOR LOWER GUARD ASSY ?	1	367.00	10.00	330.30
13220230-00	RR LICENSE PLATE TRIM PANEL ASSY <i>see</i>	1	120.00	10.00	108.00
13401407-00	REAR BUMPER WIRE ?	1	250.00	10.00	225.00
13195410-00	SMALL PROBE (PIANO BLACK) ?	2	45.00	10.00	81.00
13596478-00	PANORAMIC & REAR VIEW IMAGE MODULE ?	1	415.00	10.00	373.50
13778327-00	REAR PANEL ASSEMBLY ?	1	1,100.00	10.00	990.00
13777448-00	IMPACT BEAM, REAR ?	1	650.00	10.00	585.00
13777456-00	BACK DOOR ASSEMBLY <i>see</i>	1	3,480.00	10.00	3,132.00
13161637-00	TRIM COVER INNER LH - REAR BUMPER <i>see</i>	1	72.00	10.00	64.80
13161636-00	TRIM COVER INNER RH - REAR BUMPER <i>see</i>	1	72.00	10.00	64.80

Auto

Division of Vantage Automotive Limited)

Business Registration No. 53399829L GST Registration No. M2-0000551-1

BYD

305 Alexandra Road

159942 Singapore

Tel : 6376 8833

Fax : 6477 7398

GST Registration No. M2-0000551-1

ESTIMATE



Estimate No.

BY 6851

Date Estimated

10/09/2024

Page No. 2 of 2

Prepared By

Clement Chia Cher-Yang

REGN. NO.

SNQ6673M

CHASSIS NO.

LGXCE4CB9R2046269

REGN. DATE

30/04/2024

MODEL

ATTO 3 Ext Range

MILEAGE

8888

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
13161517-00	TRIM OF REAR BUMPER <i>repair</i>	1	174.00	10.00	156.60
13220424-00	TRIM - LOWER SURROUND REAR BUMPER ?	1	145.00	10.00	130.50
13814520-00	BUMPER BODY ASSY., REAR ?	1	1,330.00	10.00	1,197.00
13678676-00	RR LICENSE PLATE BASE ASSY X	1	60.00	10.00	54.00

Total Parts : **10,198.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
4 days
20/09/24
Res by paint

Customer Name & Signature / Company Stamp

Date

Labour 1	S\$	5,740.00
Parts	S\$	10,198.80
Labour 2	S\$	0.00
Excess	S\$	0.00
Total GST @ 9%	S\$	1,434.49
Grand Total	S\$	17,373.29

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	355Z
Vehicle Details	
Vehicle No.:	SNQ6673M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2024
Vehicle Make:	BYD
Vehicle Model:	ATTO 3 EXTENDED RANGE
Primary Colour:	Green
Manufacturing Year:	2024
Engine No.:	-
Chassis No.:	LGXCE4CB9R2046269
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$34,000.00
Original Registration Date:	30 Apr 2024
First Registration Date:	30 Apr 2024
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2034
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Apr 2034
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$89,000.00
COE Rebate Amount:	\$85,440.00
Total Rebate Amount:	\$85,440.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 23 Sep 2024

OK

BYD Atto 3 Electric Extended Range

\$165,800 Instalment \$1,390/mth

PREMIUM AD

 Apply for 2.48% loan

 Shortlist

 Loan Calculator



Overview Financial Photo Research

Depreciation	 \$17,270 / year
Reg. Date	29-Apr-2024 (9yrs 7mths 5days COE left)
Manufactured	 2024
Mileage	12 km
Transmission	Auto
Road Tax	 \$1,502 / year
Power	100.0 kW (134 bhp) View specs of the BYD Atto 3 Electric (2022)
Curb Weight	 1,750 kg
Fuel Type	Electric
Drive Range	420 km
COE	 \$89,000
OMV	 \$34,000
Dereg Value	 \$71,200 as of today