



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24090326/Rvh3m4
300 BEACH ROAD	Date:	16/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	SKN 38M
Policy No.	Z24VP05035097	Coverage	0
Claim No.	24/24/24/VP05/029864	Excess	\$0.00
Assign From	HUEY NI	Assign Date	18/09/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER 2.5 HYBRID	C.C	2487
Engine No.	A25A5549699	Year of Reg.	16/03/2021
Chassis No.	JTEAD3BH20J000309	Colour	GREY
Odometer	62928 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60R18	BRIDGESTONE	6
L/H Front Tyre	225/60R18	BRIDGESTONE	6
R/H Rear Tyre	225/60R18	BRIDGESTONE	6
L/H Rear Tyre	225/60R18	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/09/2024	Inspection Date	18/09/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A)THE MARKET VALUE IS S\$157,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days