

**Diplomat Parts Pte. Ltd.**Company Reg No. 196400304H
GST Reg No. MR-8500111-X**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte. Ltd.		Reg No/Reg Date	SMD8456R / 01/07/2016
239 Alexandra Road		Date In/Mileage	/ 0
Singapore 159930		Chassis No	RU11116042
		Engine No	L15B4036046
Contact No		Make/Model	VEZEL 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No								
RC000162		17/09/2024/ 15:52		1210/ Lim Teng Keat	33594								
Description of Goods / Services					Qty	Unit Price	Disc%	Amount					
Z	TEXT	Estimate											
	TP CLAIM												
	DOA 12/09/2024												
	SUR												
	00 REPAIR DAYS												
E	PNT88000								2250.00				
	TO REPLACE BOOT LID, REAR BUMPER AND REAR END PANEL												
	REPAIR ACCIDENT AFFECTED AREA												
E	PNT98000								1600.00				
	PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL												
M	SUNDRY								180.00				
	ANTI-RUST PROOFING												
M	SUNDRY								180.00				
	TO APPLY BODY SEALANT ON AFFECTED AREA												
E	PNT88000								280.00				
	TO REPLACE REAR WINDSCREEN												
E	PNT88000								100.00				
	TO PERFORM WATER LEAK AFTER WINDSCREEN REPLACEMENT												
M	SUNDRY								350.00				
	TO SUPPLY REVERSE SENSOR												
A	54900099		100.00										
	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM												
A	10028901		280.00										
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM												
M	SUNDRY		80.00										
	SUNDRIES												
M	SUNDRY		1093.40										
	TAIL GATE												
M	SUNDRY		115.10										
	TAIL GATE LOCK												
M	SUNDRY		40.00										
	TAIL GATE STRIKER												
M	SUNDRY		107.80										

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte. Ltd.		Reg No/Reg Date	SMD8456R / 01/07/2016
239 Alexandra Road		Date In/Mileage	/ 0
Singapore 159930		Chassis No	RU11116042
		Engine No	L15B4036046
Contact No		Make/Model	VEZEL 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
RC000162		17/09/2024/ 15:52		1210/ Lim Teng Keat	33594		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TAIL GATE WEATHER STRIP							
M	SUNDRY						32.30
TAIL GATE HONDA LOGO							
M	SUNDRY						31.10
TAIL GATE VEZEL EMBLEM							
M	SUNDRY						879.00
REAR WINDSCREEN							
M	SUNDRY						45.00
REAR WINDSCREEN SEAL TOP							
M	SUNDRY						45.00
REAR WINDSCREEN SEAL LHS							
M	SUNDRY						45.00
REAR WINDSCREEN SEAL RHS							
M	SUNDRY						45.00
REAR WINDSCREEN SEAL BOTTOM							
M	SUNDRY						46.00
REAR WINDSCREEN FASTENER							
M	SUNDRY						401.40
REAR BUMPER							
M	SUNDRY						121.50
REAR BUMPER RHS COVER							
M	SUNDRY						107.60
REAR BUMPER RHS REFLECTOR							
M	SUNDRY						32.10
REAR BUMPER RHS BRACKET							

Confirm & accepted by

Nett 8,587.30

Authorized signatory and company stamp

Total Payable 8,587.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792