



**Diplomat Parts Pte. Ltd.**

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

**ESTIMATE**

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte Ltd		Reg No/Reg Date	SMD8456R / 01/07/2016
239 ALEXANDRA ROAD		Date In/Mileage	27/09/2024/ 195594
Singapore 159930		Chassis No	RU11116042
159930		Engine No	L15B4036046
Contact No	Mobile: 91185739	Make/Model	VEZEL 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00060	Cash	08/03/2025/ 17:26	TLL	1210/ Lim Teng Keat	33594		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
Z	TEXT						
	TP CLAIM SMRT						
	DOA 12/09/2024						
	SUR						
	00 REPAIR DAYS						
E	PNT88000						625.00
	TO REPLACE BOOT LID, REAR BUMPER						
	REPAIR ACCIDENT AFFECTED AREA						
E	PNT98000						300.00
	PAINT WORK REAR BUMPER, TAIL GATE						
M	SUNDRY						50.00
	ANTI-RUST PROOFING						
M	SUNDRY						50.00
	TO APPLY BODY SEALANT ON AFFECTED AREA						
E	PNT88000						160.00
	TO REPLACE REAR WINDSCREEN						
E	PNT88000						50.00
	TO PERFORM WATER LEAK AFTER WINDSCREEN REPLACEMENT						
A	54900099						50.00
	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						
A	10028901						160.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM						
M	SUNDRY						20.00
	SUNDRIES						
E	PNT88000						250.00
	ADDITIONAL REPAIR REAR END PANEL						
E	PNT98000						200.00
	ADDITIONAL PAINT WORK RR END PANEL						
E	PNT88000						375.00
	ADDITIONAL REPAIR RR FLOOR PANEL AND PULLING						
E	PNT98000						250.00
	ADDITIONAL PAINT WORK RR FLOOR PANEL						
S	SPECIALISTJOB						160.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



**Diplomat Parts Pte. Ltd.**

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

## ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
Cycle & Carriage Leasing Pte Ltd		Reg No/Reg Date	SMD8456R / 01/07/2016
239 ALEXANDRA ROAD		Date In/Mileage	27/09/2024/ 195594
Singapore 159930		Chassis No	RU11116042
159930		Engine No	L15B4036046
Contact No	Mobile: 91185739	Make/Model	VEZEL 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00060	Cash	08/03/2025/ 17:26	TLL	1210/ Lim Teng Keat	33594

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TO SUPPLY REAR PARKING SENSOR ( HONDON VEZEL )					1093.40
M	SUNDRY TAIL GATE				31.10
M	SUNDRY TAIL GATE VEZEL EMBLEM				45.00
M	SUNDRY REAR WINDSCREEN SEAL TOP				45.00
M	SUNDRY REAR WINDSCREEN SEAL LHS				45.00
M	SUNDRY REAR WINDSCREEN SEAL RHS				45.00
M	SUNDRY REAR WINDSCREEN SEAL BOTTOM				46.00
M	SUNDRY REAR WINDSCREEN FASTENER				401.40
M	SUNDRY REAR BUMPER				121.50
M	SUNDRY REAR BUMPER RHS COVER				

Confirm & accepted by

Authorized signatory and company stamp

	Nett	4,573.40
9% GST on	4573.40	411.61
Total Payable		4,985.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792