



REPAIR PERFORMA INVOICE

Vehicle number	SLJ2786H
Make / Model	HONDA SHUTTLE
Chassis number	GP71043790
Accident date	19/6/24
Reference	2406-12

Qty	Particulars	Unit Price - SGD \$
PARTS REPLACEMENT - LIST ITEMS		
1	FRONT BUMPER	1050.50
1	FRONT BUMPER RETAINER LH	45.00
1	FRONT HEADLAMP LH	2250.50
1	FRONT FENDER LH	495.00
1	FRONT FENDER INNER SHIELD LH	180.70
1	FRONT RIM COVER LH	230.30
1	FRONT LOWER ARM LH	198.70
1	FRONT KNUCKLE ARM LH	487.00
1	FRONT KNUCKLE ARM BEARING LH	188.60
		5126.30
	Less 20%	1025.26
		4101.04
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	FRONT BUMPER CLIP	30.00
1 SET	FRONT FENDER INNER SHIELD CLIP	30.00
1	FRONT RIM	500.00
	Subtotal	560.00
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTNING SYSTEM	120.00
2	REMOVE & REPLACE FRONT UNDERCARRIAGE	150.00
3	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	150.00
4	PANEL BEATING ON AFFECTED AREAS	700.00
5	SPRAY PAINTING ON AFFECTED AREAS	700.00
6	APPLY ANTI RUST ON AFFECTED AREAS	150.00
	Subtotal	1970.00
	Grand total	6631.04

Tanpin 9249549
 WP 20/6/24 5pm
 L/S Resurvey after repair
 Tanpin 21/6/24
 3 days 2296.72
 30
 840
 3166.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1/5/2500 3 days