

Address: 2 Kaki Bukit Ave 2, #01-08, S(417921)
 Contact Person: Eric Wang
 Contact Number: 80868911
 Email: apexmotorworks911@gmail.com
 UEN: UEN: 53484790X

APEX MOTORWORKS

96893735 Adrian

To:

Date: 18/9/2024

Vehicle No: VBK 6556

Model: N Max

Xiao Chu.

Estimated Repair Cost

QTY	Parts	Amount(SGD)
1 set	Front Wind shield <i>new</i>	\$ 176.00
	Head lamp cowling <i>new</i>	\$ 150.00
	Head lamp stay <i>new</i>	\$ 85.00
	Head lamp cowling inner <i>new</i>	\$ 110.00
	Front master brake pump and reservoir <i>new</i>	\$ 176.00
	Front Handle bar <i>new</i>	\$ 380.00
	Handle bar grip <i>new</i>	\$ 85.00
	Handle bar balancer <i>new</i>	\$ 48.00
	Brake lever (SET) <i>new</i>	\$ 180.00
	Side view mirror <i>new</i>	\$ 185.00
	Front head lamp <i>new</i>	\$ 480.00
	Front signal lamp <i>Missing</i>	\$ 280.00
	Front Fork Fork <i>new</i>	\$ 850.00
	Front fork under bracket <i>new</i>	\$ 250.00
	Front fork Riser <i>new</i>	\$ 180.00
	Front cast wheel <i>new</i>	\$ 650.00
	Front wheel shaft <i>new</i>	\$ 85.00
	Front disc plate <i>new</i>	\$ 250.00
	Cover set Complete set <i>new</i>	\$ 850.00
	Cover set inner complete set <i>new</i>	\$ 650.00
	Pillion step padal <i>new</i>	\$ 85.00
	Radiator Assy <i>new</i>	\$ 550.00
	Rear tail lamp <i>new</i>	\$ 440.00
	Rear exhaust muffle <i>new</i>	\$ 680.00
	Rear exhaust cover <i>new</i>	\$ 140.00
	Rear fender <i>new</i>	\$ 198.00
	Rear license plate lamp <i>new</i>	\$ 50.00
	Rear reflector <i>new</i>	\$ 35.00
	Rear fender bracket <i>new</i>	\$ 48.00
	Rear slider <i>new</i>	\$ 120.00
	Rear mudguard <i>new</i>	\$ 258.00


Parts Sum: \$ 8,704.00

Parts Less 10%: \$ 870.40

Parts Total: \$ 7,833.60

3153

2837.70



Address: 2 Kaki Bukit Ave 2, #01-08, S(417921)
 Contact Person: Eric Wang
 Contact Number: 80868911
 Email: apexmotorworks911@gmail.com
 UEN: UEN: 53484790X

APEX MOTORWORKS

Date: 18/09/24

To:

Vehicle No: VBK 6556
 Model: NMAX 250

Estimated Repair Cost For VBK 65556		Amount(SGD)
QTY	Parts	
1 set	Rear signal lamp <i>new</i>	\$ 98.00
	Rear pillion handle <i>new</i>	\$ 148.00
	Rear foot rest pedal <i>new</i>	\$ 105.00
	Front leg shield <i>new</i>	\$ 351.00
	Less 10%	\$ 315.90
	SPECIAL NETT.	\$ 1,850.00
	Rear absorber <i>new</i>	\$ 15.00
	Front brake disc mounting bolts <i>new</i>	\$ 15.00
	Caliper mounting bolts <i>new</i>	\$ 15.00
	Front brake master pump bolts <i>new</i>	\$ 15.00
	Front fender mounting <i>new</i>	\$ 15.00
	Front cowling mounting bolts and nuts <i>new</i>	\$ 15.00
	Radiator mounting bolts <i>new</i>	\$ 50.00
	Emblem <i>new</i>	\$ 95.00
	Step pad <i>new</i>	\$ 2,085.00
	SPECIAL NETT	\$ 2,085.00
	LABOUR	
	Labour to remove and replace affected components <i>500</i>	\$ 500.00
	Spray paint	\$ 500.00
	Chassis alignment	\$ 500.00
	LABOUR	\$ 1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts Sum: \$ 8,149.50
 SPECIAL NETT \$ 2,085.00
 LABOUR \$ 600.00
 TOTAL \$ 10,834.50

Adrian L
 H/S 18/09/24
 0424p

total: 3387.7
 L/S: 27K

2-71