

LEE BROTHERS AUTOMOTIVE PTE LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

190 CLEMENCEAU AVE

#03-01 SINGAPORE SHOPPING CENTRE

SINGAPORE 239924

SJP626S

ESTIMATE

VEHICLE NO : SMF4166T

MAKE/MODEL : SKODA KODIAQ

ACC DATE : 17/09/2024

Not Authorized
du
morris
18/9/24
2/c \$13,000
Abraham. After repair
9 days.

PARTICULAR		UNIT PRICE		AMOUNT	
QTY		SS		SS	
	<u>LIST PRICE</u>				
1	1 TAILGATE	4306.95	4,461.23	Body DD	4,461.23
2	1 TAILGATE LOGO		123.05	su	123.05 X
3	2 TAILGATE LAMPS -R/L		647.97	su/cro	1,295.94
4	1 TAILGATE INNER LOCK		251.08	twi	251.08
5	1 TAILGATE INNER LOCK ACTUATOR		306.84	daye	306.84
6	1 TAILGATE INNER TRIM BOARD		381.63	nn	381.63 X
7	2 TAILGATE LICENCE LAMPS		89.95	nn	179.90 X
8	2 TAILGATE HINGES		110.25	nn	220.50 X
9	2 TAILGATE DAMPER		181.95	nn	363.90 X
10	1 TAILGATE W/STRIP		241.52	su	241.52 X
11	2 TAILLAMPS -R/L		897.91	su	1,795.82 X
12	1 REAR BUMPER		1,899.61	de/rom	1,899.61
13	1 REAR BUMPER LOWER SPOILER		686.93	cni	686.93
14	1 REAR BUMPER TOW COVER		41.50	cni	41.50
	1 REAR BUMPER TOP COVER		210.63	de	210.63
15	2 REAR BUMPER REFLECTOR -CTR		211.50	cni	423.00
16	2 REAR BUMPER REFLECTOR -R/L		191.65	cni	383.30
17	2 REAR BUMPER PDC SENSOR		262.45	multifunction	524.90
18	6 REAR BUMPER PDC SENSOR HOLDER	150	37.50	nn	225.00
19	1 REAR BUMPER TOP GUIDE -CTR		210.50	twi	210.50
20	2 REAR BUMPER SIDE GUIDE -R/L		115.00	su	230.00 X
21	1 REAR BUMPER REINFORCEMENT	641.35	920.50	su	920.50
22	1 REAR END PANEL	856.05	1,377.53	de/rom	1,377.53
23	1 REAR FOOT - ACTIVATED SENSOR		266.43	nn	266.43 X
24	2 REAR FENDER PROTECTOR -R/L		551.00	nn	1,102.00 X
25	1 REAR WIPER MOTOR		595.60	nn	595.60 X
26	1 FRONT BUMPER	1998.85	2,150.83	de/rom	2,150.83
27	1 FRONT BUMPER GRILLE		296.79	rom	296.79
28	1 FRONT BUMPER SPONGE		231.50	rom	231.50
29	1 FRONT BUMPER REINFORCEMENT		1,179.76	nn	1,179.76 X
30	1 FRONT BUMPER GRILLE ASSY		681.41	twi/rom	681.41
					23,259.13
				Less 5%	1,162.96
					22,096.17

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>SPECIAL NETT ITEMS</u>			
1	1 (SET) FRONT BUMPER CLIP	60.00	60.00
2	1 (SET) FRONT NUMBER PLATE WITH HOLDER	80.00	80.00
3	1 (SET) TAILGATE GLASS SEALANT	80.00	80.00
4	1 (SET) REAR BUMPER CLIP	60.00	60.00
5	1 (SET) REAR NUMBER PLATE WITH HOLDER	80.00	80.00
6	1 REAR REVERSE CAMERA	450.00	450.00
			810.00
<u>LABOUR CHARGES :</u>			
1	TO REMOVE, REFIX TAILGATE GLASS		180.00
	TO TRANSFER TAILGATE PARTS		150.00
2	TO CHECK FRONT & REAR ELECTRICAL WIRING		100.00
3	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR		120.00
4	TO TUFF KOTE		120.00
5	TO DIAGNOS EARSE FAULT MEMORY AFTER REPAIR		350.00
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		1,600.00
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS		1,800.00
			4,420.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 27,326.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-15397-13
102
13857-42
160
2320
16337-42
202
13068.