

ASS. REC. BY:

REF:

Smo/

CS/SMO24090331/Kvp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GU 1064R

Policy No. _____


Claims No. CMTD2402989/SYH

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 87k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 26 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN600P Yr Regn: 0618

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Harrier C.C. 1998

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 136398 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEKB 36H00 J002059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 17/9/24

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.I. 18/9/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/9 21 Lm @ 3800 Cal (red 2597.53, 40%)

Date/Time, File Pass to?

: Prel. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 642H

Vehicle Details

Vehicle No.: SKN600P
Vehicle to be Exported: No
Intended Deregistration Date: 17 Sep 2024
Vehicle Make: TOYOTA
Vehicle Model: HARRIER G GRADE
Primary Colour: Black
Manufacturing Year: 2018
Engine No.: 8ARZ120275
Chassis No.: JTEKB3GH00J002059
Maximum Power Output: 170.0 kW (227 bhp)
Open Market Value: \$33,308.00
Original Registration Date: 08 Jun 2018
First Registration Date: 08 Jun 2018
Transfer Count: 1
Actual ARF Paid: \$38,632.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Jun 2028
PARF Rebate Amount: \$25,110.00

Intended COE Rebate Details

COE Expiry Date: 07 Jun 2028
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$37,989.00
COE Rebate Amount: \$14,146.00
Total Rebate Amount: \$39,256.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 17 Sep 2024

OK

Date: 17/9/2024
Vehicle No: SKN600P
Model: TOYOTA HARRIER
Chassis: JTEKB3GH00J002059
Reg.Year: 2018

Third Party Insurer: SOMPO
Third Party Veh No: GU1064R
Date of Accident: 17/9/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LH SIDE MIRROR ASSY <i>1520.80</i>			\$ <i>CM</i> 2,096.00
	LH SIDE MIRROR COVER			\$ <i>MT</i> 132.70
	LHF DOOR <i>1881.30</i>			\$ <i>B</i> 2,555.00
	LHF DOOR HANDLE			\$ <i>PD/12</i> 531.00
	LHF DOOR HANDLE INNER HOLDER			\$ <i>0.1</i> 132.00
	LHF FENDER			REPAIR
	LHR DOOR			REPAIR
	LH SIDE DOOR MEMBER			REPAIR
SUB TOTAL				\$ 5,446.70
Less 25%				-\$ 1,361.68
PARTS TOTAL				\$ 4,085.03

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	DOOR INNER TRIM CLIPS			\$ <i>RM</i> 50.00
S/N TOTAL				\$ 50.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix Side affected areas			\$	800.00	<i>400</i>
To perform wiring checks on electrical systems			\$	30.00	<i>201</i>
To remove, putty, repair, sand and respray affected areas			\$	750.00	<i>460</i>
To remove, replace & reinstall Door inner mechansim	2	30	\$	60.00	<i>✓</i>

LABOUR TOTAL \$ 1,640.00

JONATHAN TOTAL \$ 5,775.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



*Not Withhold
1/1/2024 8300ch
Merry After Paint
4 days*

Date: 24/9/2024
Vehicle No: SKN600P
Model: TOYOTA HARRIER
Chassis: JTEKB3GH00J002059
Reg. Year: 2018

Third Party Insurer: SOMPO
Third Party Veh No: GU1064R
Date of Accident: 17/9/2024

V# 2630

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR GLASS			<i>cut</i> \$480.00
	LHF DOOR BELT MOLDING (CHROME STRIP)			<i>nd</i> \$110.00
			SUB TOTAL	\$590.00
			LESS 25%	-\$147.50
			PARTS TOTAL	\$442.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR HANDLE CHROME PROTECTOR			<i>nd</i> \$100.00
	LHF DOOR VISOR			<i>nd</i> \$80.00
			S/N TOTAL	\$180.00

SUPPLEMENTARY

LABOUR CHARGES:

	LABOUR TOTAL	\$0.00
VIC / TING AN	TOTAL	\$622.50

Head office

8 Junc Cheng Road Singapore 191143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

0A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1063

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park ZA #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

