

Date: 17/9/2024
Vehicle No: SKN600P
Model: TOYOTA HARRIER
Chassis: JTEKB3GH00J002059
Reg. Year: 2018

Third Party Insurer: SOMPO
Third Party Veh No: GU1064R
Date of Accident: 17/9/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LH SIDE MIRROR ASSY <i>1520.80</i>			\$ <i>CM</i> 2,096.00
	LH SIDE MIRROR COVER			\$ <i>mi</i> 132.70
	LHF DOOR <i>1881.30</i>			\$ <i>R</i> 2,555.00
	LHF DOOR HANDLE			\$ <i>DD</i> 531.00
	LHF DOOR HANDLE INNER HOLDER			\$ <i>nd</i> 132.00
	LHF FENDER			REPAIR
	LHR DOOR			REPAIR
	LH SIDE DOOR MEMBER			REPAIR
SUB TOTAL				\$ 5,446.70
Less 25%				-\$ 1,361.68
PARTS TOTAL				\$ 4,085.03

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	DOOR INNER TRIM CLIPS			\$ <i>na</i> 50.00
S/N TOTAL				\$ 50.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix Side affected areas

\$ 800.00 *400d*

To perform wiring checks on electrical systems

\$ 30.00 *20d*

To remove, putty, repair, sand and respray affected areas

\$ 750.00 *460d*

To remove, replace & reinstall Door inner mechansim

2 30 \$ 60.00 ✓

LABOUR TOTAL \$ 1,640.00

TOTAL \$ 5,775.03

JONATHAN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Not Withstand
1/1/2024 8300h
Money After Pay
4 days

Date: 24/9/2024
Vehicle No: SKN600P
Model: TOYOTA HARRIER
Chassis: JTEKB3GH00J002059
Reg.Year: 2018

Third Party Insurer: SOMPO
Third Party Veh No: GU1064R
Date of Accident: 17/9/2024

P# 2630

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR GLASS			<i>cut</i> \$480.00
	LHF DOOR BELT MOLDING (CHROME STRIP)			<i>nd</i> \$110.00
			SUB TOTAL	\$590.00
			LESS 25%	-\$147.50
			PARTS TOTAL	\$442.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR HANDLE CHROME PROTECTOR			<i>nd</i> \$100.00
	LHF DOOR VISOR			<i>nd</i> \$80.00
			S/N TOTAL	\$180.00

SUPPLEMENTARY

LABOUR CHARGES:

	LABOUR TOTAL	\$0.00
VIC / TING AN	TOTAL	\$622.50