

Date: 24/9/2024
Vehicle No: SKN600P
Model: TOYOTA HARRIER
Chassis: JTEKB3GH00J002059
Reg. Year: 2018

Third Party Insurer: SOMPO
Third Party Veh No: GU1064R
Date of Accident: 17/9/2024

V# 2630

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR GLASS			<i>cut</i> \$480.00
	LHF DOOR BELT MOLDING (CHROME STRIP)			<i>nd</i> \$110.00
			SUB TOTAL	\$590.00
			LESS 25%	-\$147.50
			PARTS TOTAL	\$442.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	LHF DOOR HANDLE CHROME PROTECTOR			<i>nd</i> \$100.00
	LHF DOOR VISOR			<i>nd</i> \$80.00
			S/N TOTAL	\$180.00

SUPPLEMENTARY

LABOUR CHARGES:

	LABOUR TOTAL	\$0.00
VIC / TING AN	TOTAL	\$622.50

Head office

8 Jang Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

0A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1963

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park ZA #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

