

Date : 04/09/2024

India International Insurance Pte Ltd
Attn: Motor Claims Department

Vehicle number : SMZ8845K
Make and model : IONIQ ELECTRIC
Registration Date : 24/05/2021
Chassis number : KMHC851JUMU079037
Engine number : EM10M1U004AJ

Claim Officer : Robyn
Job No. :
Owner name : KOMOCO CAR REI
Date of Acc : 03/09/2024
Policy number : B400002657 MCY
Claim Type : TP

Items :		2nd	Estimate	Revised
1	FRT BUMPER CLIP X10	865952T500	\$ 20.00	
2	COVER-FR BUMPER	86511G2500	\$ 554.00	
3	MOULDING-FRONT BUMPER CTR,UPR	86585G7500	\$ 139.00	
4	MOULDING-FRONT BUMPER,LH	86563G2550	\$ 55.00	
5	LAMP ASSY-DAY RUNNING LIGHT,LH	92207G2100	\$ 643.00	
6	BRACKET-FR BUMPER SIDE,LH	86513G2000	\$ 20.00	
7	PANEL-FENDER,LH	66311G2000	\$ 589.00	
8	LAMP ASSY-HEAD,LH	92101G2230	\$ 2,111.00	
9	REINF-FENDER APRON UPR,LH	64533G2000	\$ 130.00	
10	BEAM COMPLETE-FR BUMPER	64900G2000	\$ 1,484.00	
11	CARRIER ASSY-FRONT END MODULE	64101G2000	\$ 950.00	
12	BRACKET ASSY-FENDER MTG FR,LH	64615G2000	\$ 42.00	
13	BRACKET ASSY-FENDER MTG FR,RH	64625G2000	\$ 42.00	
			\$ 4,131.00	
Less 20% Discount			\$ 826.20	
Material total			\$ 3,304.80	

Vehicle number

Body,Paint & Labour Items :		Estimate	
1	To carry out accident body repair - FRT BUMPER / FRT LH FENDER / SUPPORT PANEL	\$	2,100.00
2	Complete putty and spray paint all affected areas - FRT BUMPER / FRT LH FENDER / FRT LH BUMPER GARNISH CTR / FRONT BUMPER MOULDING LHS	\$	1,600.00
Labour Charges:	2nd	Estimate	Revised
3	TO REALIGN FRT BOTH HEADLAMP (S.NETT)	\$	40.00
4	TO REPAIR FRT LH FENDER APRON (S.NETT)	\$	420.00
5	TO TOP UP A/C GAS (S.NETT)	\$	140.00
6	TO REPAIR FRT CHASIS MEMBER (S.NETT)	\$	420.00
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00
8	TO PERFORM PREPROGRAMME AFTER ACCIDENT REPAIR (S.NETT)	\$	180.00
9	SUNDRIES	\$	40.00
Total Labour		\$	5,120.00
Total Parts		\$	3,304.80
Excess		\$	-
		\$	8,424.80
Add GST 9%		\$	758.23
Grand Total		\$	9,183.03

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***