

ASS. REC. BY:

T. J. J. J.

REF:

CS/FC/24090334/Top3

ASSIGNMENT

CoE 2027/03

From:

Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$30K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 9468C

Yr Regn:

2007, 04

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c

2354

Colour

Orange

A/C: Insured / Std / NI / NA

Sp. Reading

194150

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRB18507 G 203869

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS: ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front

6

Rear

C

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

18/4/24

Survey held at

Win Auto

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/G / ☐ Rooftop or

Frt N/S, U/G, O/S

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit \$15K

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Format:

Lump Sum / L.B.E. (\$

**Adjustment of Spare Parts Costs for Repairs SLC 9468S
HONDA ODESEY**

Item	Qty	Vehicle parts description	Estimate by
List Items			
1	1	front bumper	\$1,000.00 <i>de</i> ✓
2	2	front bumper side retainer LH & RH	\$120.00 <i>de</i> ✓
3	1set	front bumper clips	\$30.00 <i>nel</i> ✓
4	1	front bumper reinforcement	\$520.00 <i>bt</i> ✓
6	1	front grille fasteners	\$30.00 <i>nel</i> ✓
7	1	front grille honda logo emblem	\$90.00 <i>mis</i> ✓
8	1	front bonnet	\$1,350.00 <i>Rx</i>
9	1	front bonnet inner lock	\$255.00 <i>?</i>
	1	front fender LH	\$800.00 <i>bt</i> ✓
10	1	front support panel	\$400.00 <i>?</i>
11	1	front support panel top garnish	\$80.00 <i>?</i>
12	1	support panel top garnish fasteners	\$40.00 <i>?</i>
	1	front LH wheel house support panel	\$1,180.00 <i>bnc</i> ✓
13	2	front headlamp LH & RH	\$2,000.00 <i>cra</i> ✓
14	2	front headlamp LH & RH bracket holder	\$250.00 <i>dis</i> ✓
#REF!	1	front fender inner shield LH	\$200.00 <i>dn</i> ✓
25	2	front fog lamp LH & RH	<i>RHX</i> \$450.00 <i>LH dis</i> ✓
26	2	front fog lamp cover LH & RH	\$180.00 <i>mis</i> ✓
	1	front LH absorber <i>shock absorber</i>	\$480.00 <i>bt</i> ✓
	1	front LH wheel bearing	\$380.00 <i>bt</i> ✓
	1	front LH knuckle arm	\$580.00 <i>bt</i> ✓
	1	front LH lower arm	\$520.00 <i>bt</i> ✓
	1	front LH absorber linkage	\$300.00 <i>?</i>
	1	front LH wheel hub	\$380.00 <i>bt</i> ✓
	1	front LH steering rack	\$450.00 <i>bt</i> ✓
	1	front LH side mirror assy whole set	\$1,080.00 <i>cra</i> ✓
	1	front LH door	\$1,050.00 <i>Rx</i>
	1	front LH door quarter glass	\$350.00 <i>?</i>
	1	front windscreen	\$1,250.00 <i>cny</i> ✓
	1	front windscreen moulding	\$255.00 <i>nel</i> ✓
	1	front washer tank assy	\$225.00 <i>?</i>
	1	front air bag LH assy	\$880.00 <i>act</i> ✓
	1	front air bad RH assy	\$780.00 <i>act</i> ✓
	1	front air bag module	\$550.00 <i>act</i> ✓
	1	front air bag LH cover	\$280.00 <i>act</i> ✓
	1	front air bag controller	\$680.00 <i>act</i> ✓
	1	front air bag spring	\$280.00 <i>act</i> ✓
	1	front dashbaord garnish component	\$400.00 <i>?</i>
<i>Front drive shaft bt</i> ✓ <i>4750</i>			

Driver seat belt act - 9500
passenger seat belt ? 9500

1	rear bumper	\$980.00 <i>de</i>
1	rear LH tailamp	\$700.00 <i>ent</i>
1	front LH side skirt garnish assy	\$500.00 <i>Rx</i>

\$22,305.00

LESS 20%

\$446.10

\$17,844.00

Special nett item

1	number plate	\$40.00 <i>ent</i>
2	front rim LH	\$350.00 <i>bl</i>
	front tyre LH	\$280.00 <i>ent</i> - 80%
	front windscreen sealant	\$60.00 <i>net</i>

Total parts

\$730.00

Adjustment of Labour Costs for Repairs

Spraying of affected areas,

\$1,400.00 *1200*

Remove / Refix dashboard & airbag

\$500 *300*

Carry out body cavity preservation

\$100.00 *50*

Remove / Refix under carriage

\$300 *150*

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, rear fender LH/RH, bootlid, end panel etc

\$1,600.00 *1200*

Check wiring

\$40.00 *✓*

to realign headlamp focus

\$40.00 *30*

to top up air con gas

\$40.00 *?*

to top up coolant

\$40.00 *?*

Total labour

\$3,260.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjik 97415749
wp 18/9/24 @ 4pm
cls Resing after repair
Tanjik c lkkauto.com
10 days