

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2400361
Date: 16 Sep 2024
Veh Reg No: SNC9191R
Make/Model: TOYOTA CAMRY
HYBRID 4DR SEDAN
(AT) ELEGANCE
Chasis No: JTNB23HK103101973
Reg. Date: 06/08/2021
Your Ref No: SLX153X

Claim Type: Third Party
Accident Date: 14/09/2024
TP Veh Reg No: SLX153X

Estimate Repair Cost to Vehicle No :SNC9191R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID		
2	1 PC BOOT LID LOGO		
3	1 PC BOOT LID "TOYOTA" EMBLEM		
4	1 PC BOOT LID "HYBRID" EMBLEM		
5	1 PC BOOT LID LAMP LH		
6	1 PC BOOT LID LAMP RH		
7	1 PC BOOT LID LOCK		
8	1 PC BOOT LID LOCK CHECKER		
9	1 PC BOOT LID RUBBER		
10	1 PC BOOTLID TRIM		
11	1 PC REAR PANEL		
12	1 PC REAR PANEL TRIM		
13	1 PC SPARE TYRE PANEL TOOL SPONGE		
14	1 PC REAR SPARE TYRE HARDBOARD COVER		
15	1 PC SPARE TYRE PANEL LOWER COVER		
16	1 PC REAR FENDER TRIM RH		
17	1 PC REAR FENDER TRIM LH		
18	1 PC TAIL LAMP LH		
19	1 PC TAIL LAMP - RH		
20	1 PC REAR BUMPER		
21	1 PC REAR BUMPER REINFORCEMENT		
22	1 PC REAR BUMPER SPONGE		
23	2 PCS REAR BUMPER SIDE RETAINER		
24	1 PC REAR BUMPER SIDE BLACK TRIM		
25	1 PC REAR BUMPER ANTENNA SENSOR		
26	2 PCS REVERSE SENSORS		
27	2 PCS REAR BUMPER SPOILER LOWER TRIM		
		0.00	0.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2400361
Date: 16 Sep 2024
Veh Reg No: SNC9191R
Make/Model: TOYOTA CAMRY
HYBRID 4DR SEDAN
(AT) ELEGANCE
Chasis No: JTNB23HK103101973
Reg. Date: 06/08/2021
Your Ref No: SLX153X

Claim Type: Third Party
Accident Date: 14/09/2024
TP Veh Reg No: SLX153X

Estimate Repair Cost to Vehicle No :SNC9191R

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Special Net		
28	1 PC REAR NUMBER PLATE		
29	1 SET BOOTLID TRIM CLIPS		
30	1 SET REAR PANEL TRIM CLIPS		
31	1 SET REAR FENDER TRIM CLIPS RH		
32	1 SET REAR FENDER TRIM CLIPS LH		
33	1 SET REAR BUMPER CLIPS		
		0.00	0.00
	Labour		
34	1 TO CHECK WIRING	50.00	
35	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
36	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
37	1 TO SPRAY ANTI RUST PROOF	80.00	
38	1 (REAR) TO SPRAY PAINTING	1,200.00	
39	1 TO REMOVE AND REFIT INNER TRIM	100.00	
40	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,400.00	
		2,990.00	2,990.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2400361
Date: 16 Sep 2024
Veh Reg No: SNC9191R
Make/Model: TOYOTA CAMRY
HYBRID 4DR SEDAN
(AT) ELEGANCE
Chasis No: JTNB23HK103101973
Reg. Date: 06/08/2021
Your Ref No: SLX153X

Claim Type: Third Party
Accident Date: 14/09/2024
TP Veh Reg No: SLX153X

Estimate Repair Cost to Vehicle No :SNC9191R

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 2,990.00
	Add GST @ 9%		269.10
	Total Amount Payable		<u>S\$ 3,259.10</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED FIFTY NINE AND CENTS
TEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE