

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24090338/UPA3Q2**Date:** 20/12/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571
Claimant Vehicle No : GBJ820Z **Insured Vehicle No :** SLS8915R
 Date of Loss: 29/08/2024 Nature of Claim: TP Claim No: MFL2024D0010145

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ820Z**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) Engine No: 1KD2831785
 Reg. Date: 14/12/2018 (Man. Year: 2018) Chassis No: JTFHT02P500246358
 Colour: Silver Odometer: 159766 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: RIVO 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: RIVO 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,997.50	1,909.65	1,087.85	36.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	850.00	450.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,297.50	2,759.65	1,537.85	35.78
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	4,297.50	2,200.00	2,097.50	48.81
+ GST 9.00/9.00% (S\$)	386.78	198.00	188.78	48.81
Nett Amount (S\$)	4,684.28	2,398.00	2,286.28	48.81
+ Car Rental (3.0 x S\$100.00/day + 9.00% GST) (S\$)		327.00		
(S\$)		2,725.00		
Liabe Amount (50.00%) (S\$)		1,362.50		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,364.68		
Global Sum Settlement (S\$)		1,350.00		

INSPECTION

Date of Assignment: 20/09/2024
 Date Inspected: 20/09/2024 Inspected At: Think One Autocare Pte Ltd (HQ)
 Estimated Period of Repair: 3.0 days No. 60 Jalan Lam Huat #02-32, Carros Centre
 Singapore 737869

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Oct 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ820Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Bent	820.40 F	*820.40 FL
2	1		*FRONT BONNET EMBLEM	Necessary	75.60 F	*75.60 FL
3	1		*RIGHT FRONT CORNER PANEL	Repair	263.60 F	*- FL
4	1		*RIGHT HEADLAMP	Cracked	880.60 F	*880.60 FL
5	1		*FRONT BUMPER	Cut / Deformed	729.60 F	*729.60 FL
6	1		*FRONT BUMPER RETAINER (RIGHT)	Not Necessary	197.70 F	*- FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
					Sub Total (\$\$)	2,997.50 2,536.20
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 626.55
					Total Parts (\$\$)	2,997.50 1,909.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING	New	50.00	20.00
2	ANTI RUST PROOF	New	50.00	30.00
3	PANEL BEATING	New	500.00	300.00
4	PAINT WORK	New	700.00	500.00
Gross Labour Cost (\$\$)			1,300.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >