

Vehicle: GBJ820Z

Make & Model: TOYOTA HIACE

Chassis No: JTFHT02P500246358

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Front Bonnet	1PC		\$ 820.40	no/surf
2	Front Bonnet Emblem	1PC		\$ 75.60	new
3	Right Front Corner Panel	1PC		\$ 263.60	RX
4	Right Headlamp	1PC		\$ 880.60	cm
5	Front Bumper	1PC		\$ 729.60	cut/re
6	Front Bumper Retainer (Right)	1PC		\$ 197.70	11X
7	Front Bumper Clips	1set		\$ 30.00 SN	new ✓ s/n
8				252	
Labour					
1	Check Wiring			\$ 50.00	20
2	Anti Rust Proof			\$ 50.00	30
3	Panel Beating			\$ 500.00	300
4	Paint Work			\$ 700.00	500

Not Authorized
in
morang
20/9/24
h/s #2200/
3 days
take plus after

P.2506.2
252
1878.65
30
850

2889.65
203
2207

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: