



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24090339/Evp3m4
16 RAFFLES QUAY	Date:	07/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3802Y	Veh. Inspected	SML 9430R
Policy No.	-	Coverage	0
Claim No.	D24007981MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	18/09/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS PLUS (AUTO)	C.C	1798
Engine No.	2ZR0D50751	Year of Reg.	12/06/2019
Chassis No.	JTDZS3EU90J040666	Colour	BLACK
Odometer	439053 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	TRIANGLE	6
L/H Front Tyre	205/60R16	TRIANGLE	6
R/H Rear Tyre	205/60R16	TRIANGLE	6
L/H Rear Tyre	205/60R16	TRIANGLE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/09/2024	Inspection Date	19/09/2024
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days