



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 5737986

HP: 98888885

Estimation

Date: 19/9/2024

Vehicle: SML9430R

Make / Model: TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount
1	REAR BUMPER / OP	1	\$ 658.00	\$ 658.00
2	REAR BUMPER SIDE RETAINER LH / BP	1	\$ 112.00	\$ 112.00
3	REAR BUMPER LIP / DEF	1	\$ 728.90	\$ 728.90
4	REAR FENDER LH X 11	1	\$ 698.00	\$ 698.00
5	TAILAMP LH X 11	1	\$ 598.00	\$ 598.00
				\$ 2,794.90
			Less 20%	\$ 558.98
			Total	\$ 2,235.92
	S/Nett items:			
1	REAR BUMPER CLIPS / 111	1	\$ 50.00	\$ 50.00
	Reverse Sensor / 111 \$200			\$ 50.00
	Labour to: REAR			
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 100.00	\$ 100.00
3	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
4	PANEL BEATING ON AFFECTED AREAS	1	\$ 400.00	\$ 400.00
				\$ 1,080.00
			Parts Replacement Amount	\$ 2,285.92
			Total Amount for Labour	\$ 1,080.00
			Total Amount	\$ 3,365.92

Steve (LKK)

19/9/24, 10:00am

m 11

L/S

L J AL L
3 41

3565.92

1470.75

L/S - 1176.60
= 1200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: