

ESTIMATED ACCIDENT REPAIR COST



TOWER TRANSIT

Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	16:59	BUS REGISTRATION NUMBER	SBS3372H
ACCIDENT DATE	13-Sep-24	BUS TYPE (SD/DD)	DD
BUS CAPTAIN NAME	PANG MAN LIN	BUS ROUTE NO.	
THIRD PARTY CLAIM AGAINST	SMRT	BUS ADVERT (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	CCTV BUZZER AND BRACKET <i>com</i>	1	\$ 836.00
		9% GST	\$ 75.24
		PARTS TOTAL COST	\$ 911.24

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
TO DISMANTLE & REPLACE :-		
• DISMANTLE AND REPLACE ITEM NO : 1	400	\$ 650.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :-		
• OSR DOME	1075 325	\$ 650.00
SPRAY PAINTING :-		
• OSR DOME	350	\$ 640.00
SPRAY PAINTING \$640 PER PANEL	9% GST	\$ 174.60
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST	\$ 2,114.60

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

DATE IN	13/Sep/2024
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	5

BUS TYPE (SD / DD)	DD
--------------------	----

LOSS OF USE COST

\$2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

836

1075

1911

Same
400 1075
3 days
19/09/24
Reg after repair

SUMMARY

SECTION NO.	COST
1	\$ 911.24
2	\$ 2,114.60
3	\$ 2,000.00
TOTAL	\$ 5,025.84