

SANPOH APPRAISER

17 Pioneer Road North #01-89 Lokyang Light Industries Park Singapore 628465

Tel: 6457 2625 Fax: 6252 8459

Registration No.: 53458439W

Email: sanpohappraiser@gmail.com

To : Seah Zhen Long Jeremy
Blk 541 Hougang Avenue 8
#05-1213
Singapore 530541

Invoice : 00008
Date : 13/12/2022
Our Ref : SA/2022/00008

VEHICLE REG. NO : SML7843X

VEHICLE MAKE/MODEL : Honda Fit

INSPECTION REPORT FEES \$ 2,400.00

Singapore Dollars : Two Thousand Four Hundred Only

SANPOH APPRAISER



A handwritten signature in black ink, written over the circular seal and extending to the right.

SANPOH APPRAISER

17 Pioneer Road North #01-89 Lokyang Light Industries Park Singapore 628465

Tel: 6457 2625 Fax: 6252 8459

Registration No.: 53458439W

Email: sanpohappraiser@gmail.com

To : Seah Zhen Long Jeremy
Blk 541 Hougang Avenue 8
#05-1213
Singapore 530541

Date : 13/12/2022
Our Ref : SA/2022/00008

Dear Sirs,

THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle **SML7843X** on 4 Nov 2022.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Yee Auto Service** for **\$15,277.68** as per our attached schedule have been inspected thoroughly each and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$12,200.00** lump sum corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **EIGHT (6) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,



SANPOH APPRAISER

SANPOH APPRAISER

Vehicle No.: SML7843X
Model: Honda Fit

Our ref: SA/2022/00008

No	Descriptions		Conditions	Repairer's Est.	Our Revised.
Spare Parts					
1	Rear bumper	595 /	1	dented	\$ 1,825.70 \$ 1,825.70
2	Rear bumper clips	30 /	10	necessary	\$ 100.00 \$ 100.00
3	Rear bumper side retainer - LH	60 /	1	dented	\$ 146.20 \$ 146.20
4	Rear bumper side retainer - RH	60 /	1	dented	\$ 146.20 \$ 146.20
5	Rear bumper lamp - RH x nn		1	dented/repair	\$ 368.50 -
6	Rear fender - RH x Repair		1	dented	\$ 1,750.70 \$ 1,750.70
7	Rear fender arch garnish - RH x nn		1	dented/repair	\$ 498.50 -
8	Rear fender dust cover - RH x nn		1	dented	\$ 385.20 \$ 385.20
9	Rear door - RH x nn		1	dented/repair	\$ 1,425.60 -
10	Rear door arch garnish - RH x nn		1	dented/repair	\$ 498.50 -
11	Rear shock absorber - RH x nn		1	dented	\$ 698.50 \$ 698.50
12	Rear axle beam x nn		1	dented	\$ 3,285.70 \$ 3,285.70
13	Rear wheel bearing - RH x nn		1	damaged	\$ 358.20 \$ 358.20
14	Rear fender inner garnish - RH x nn		1	dented	\$ 725.20 \$ 725.20
15	Rear fender air dust - RH x nn		1	dented	\$ 175.00 \$ 175.00
16	Rear end panel x nn		1	dented/repair	\$ 1,150.10 -
17	Rear taillamp - RH x nn		1	grazed/cut	\$ 725.50 \$ 725.50
					\$ 14,263.30 \$ 10,322.10
		-20%			\$ 2,064.42
					\$ 14,263.30 \$ 8,257.68
Net Price					
18	Rear wheel rim - RH	300 /	1	sliced	\$ 1,200.00 \$ 1,100.00
19	Rear tyre - RH x nn		1	wall cut	\$ 350.00 \$ 300.00
Labour					
20	To dismantle & replace damaged parts, panel beat where necessary.		1	300	\$ 1,800.00 \$ 1,600.00
21	To supply painting material.		1	400	\$ 600.00 \$ 500.00
22	To putty, apply primer & spray-paint on the affected portion.		1	20	\$ 1,800.00 \$ 1,800.00
23	To apply rust - proofing on repaired, replaced panel.		1	20	\$ 220.00 \$ 220.00
24	To wheel alignment.		1	80	\$ 280.00 \$ 250.00
25	To remove/renew L/H rear undercarriage.		1	x	\$ 600.00 \$ 500.00
26	To computer reset.		1	x	\$ 650.00 \$ 600.00
27	To check wiring functions.		1	30	\$ 150.00 \$ 150.00
				Total Amount	\$ 21,913.30 \$ 15,277.68

Yours faithfully,

Note : The repairer has agreed to undertake the repairs at our adjusted amount of **\$12,200.00 lump sum** corresponding

4 days




SANPOH APPRAISER

to supply of parts, labour & spray painting charges.

Under normal circumstances, the estimated repair period would be 6 days.

Pursuant to your instruction we have not authorised repairs on your behalf.