

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721
Phone 8263 6295 (Steven) Fax 6266 2881

ESTIMATE

DATE 10-Oct-24
Vehicle No JSA9700
Make/Model Toyota Vios
Date of Accident 16-Sep-24

Bill To:

Saroja A/P Bongasamy
c/o 176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721

NO	DESCRIPTION	AMOUNT
LIST ITEMS		
1	Rear bootlid BT ✓	\$ 852.40
2	Rear bootlid hinge x 2 @97.40 R	194.80 X
3	Rear bootlid outer moulding cra/cld ✓	201.40
4	Rear bootlid lock dd X not damaged	198.60
5	Rear bootlid striker R	29.90 X
6	Rear bootlid logo nec ✓	57.00
7	Rear bootlid VIOS logo nec ✓	61.00
8	Rear bootlid X logo nec ✓	57.00
9	Rear bootlid weatherstrip 50% dd / dist X not damaged / not nec	166.40
10	Taillamp assy x 2 @445.80 cra ✓	891.60
11	Taillamp panel BT ✓	710.20
12	Taillamp panel garnish mtg dist ✓	198.70
13	Rear bumper assy Buc ✓	565.00
14	Rear bumper retainer x 2 cra ✓	263.80
15	Rear bumper reinforcement R	322.30 X
16	Rear fender RH R	894.80 X
Less 25%		5,664.90
		1,416.23
S/NETT ITEMS		
1	Rear bumper reverse sensor Svc	300.00 X
2	Rear bumper clips nec ✓	20 60.00
3	Rear number plate cra ✓	35 50.00
4	Rear windscreen sealant nn	40.00
LABOUR & MISC		
1	To dismantle/renew accident damaged portion. To panel beat, straighten and align replacement parts	1,200.00 800 ✓
2	To check wiring	40.00 20 ✓
3	To rust proof affected portion after repair	100.00 60 ✓
4	To remove & refit rear windscreen	150.00 X nn
5	To remove & refit interior trim, garnish & etc	150.00 80 ✓
6	Supply spray paint materials & respay affected areas	1,500.00 1000 ✓
7	Remove & refit rear reverse sensor	80.00 50 ✓
TOTAL		\$ 7,918.67

THIAM HENG HUAT PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: