

ASS. REC. BY:

REF:

CIP / CS/LIP24090347/Kvh3cd

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: XD 6820E

Policy No.

Claims No. BVS24/0666

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

JSA 9700

Yr Regn:

2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios

C.C.

1496

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

102113

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PN153 SYI 10.3010443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

16/9/24

D.O.I.

19/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 EN not ready, acc report not ready

14/10 11:00 @ 4100k Cash

30/10/24 LS \$3950 confirmed with Jenny (Red 3968.67, 50%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

K2RAZBF6

No. Pendaftaran : JSA9700

No. ID : 750622015702

Nama Pemunya Berdaftar : SAROLA A/P HONGSANY

Alamat : NO 26, JLN SURIA 37, BANDAR SERI ALAM
81750 MASAI JOHOR

No. Chasis/No. Enjin : PH133YF103010443 / 2HR0M09048

Buatan/Nama Model : TOYOTA / VIOS 1.5G X AT

Kedayaan Enjin : 1496

Bahan Bakar : PETROL

Status Asas : PEMASANGAN TEMPATAN

Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU

Jenis Badan/Tahun Dibuat : MOTOKAR / 2017

Tarikh Pendaftaran : 26/02/2017

B. D. M/E. Q. X/GTM

Syarat Pendaftaran 1

Syarat Pendaftaran 2

Syarat Pendaftaran 3



TOKIO MARINE
INSURANCE GROUP

TOKIO MARINE INSURANS (MALAYSIA) BERHAD

198601000381 (149520-U)
SUITE 9.2, LEVEL 9, MENARA PELANGI, NO.2, JALAN KUNING, TAMAN PELANGI, 80400 JOHOR BAHRU, JOHOR,
MALAYSIA
Tel No. 07-3363071 / 3360137 Fax No. 07-3365901
Website: www.tokiomarine.com



Tell us your experience with
Tokio Marine

Benefit(s) payable under eligible certificate/policy/product is(are) protected by PIDM up to limits. Please refer to PIDM's TIPS Brochure or contact Tokio Marine Insurans (Malaysia) Berhad or PIDM (visit www.pidm.gov.my).

Manfaat-manfaat yang dibayar di bawah sijil/polisi/produk yang layak adalah dilindungi oleh PIDM sehingga had perlindungan. Sila rujuk Brosur Sistem Perlindungan Manfaat Takaful dan Insurans PIDM atau hubungi Tokio Marine Insurans (Malaysia) Berhad atau PIDM (layari www.pidm.gov.my).

MOTOR INSURANCE SCHEDULE / JADUAL INSURANS MOTOR

CLASS / POLICY : Kelas / Polisi POLICY NO. : No. Polisi E INSURED & ADDRESS : Milik & Alamat	PC PRIVATE CAR - PRIVATE USE V6207844 (VS163912) SAROJA A/P BONGASAMY NO 26 JALAN SURIA 37 BANDAR SERI ALAM MASAI 81750 JOHOR	DATE : Tarikh ACCOUNT NO. : No. Akaun AGENT NAME : Nama Ejen	29-03-2024 JB-00016810 SHOWA AUTO TRADE (M) SDN BHD
MOD OF INSURANCE : MPOH PERLINDUNGAN	a. FROM 01-04-2024 (00:00:01 AM) TO 31-03-2025 DARI HINGGA (BOTH DATES INCLUSIVE) / (TERMASUK KEDUA-DUA TARIKH) b. ANY SUBSEQUENT PERIOD FOR WHICH THE INSURED SHALL PAY AND THE COMPANY SHALL AGREE TO ACCEPT A RENEWAL PREMIUM MANA-MANA TEMPOH SELANJUTNYA YANG MANA PIHAK DIINSURANSKAN HENDAKLAH MEMBAYAR DAN SYARIKAT HENDAKLAH BERSETUJU MENERIMA SATU PREMIUM PEMBAHARUAN	PREMIUM : PREMIUM NCD 55.00% : DISKAUN TANPA TUNTUTAN (WFF:01-04-2024) EXT. PREMIUM : PREMIUM TAMBAHAN SERVICE TAX 8.00% : CUKAI PERKHIDMATAN 8.00% : PREMIUM MOTOR : MOTOR PREMIUM STAMP DUTY : DUTI SETEM TOTAL PAYABLE : JUMLAH PEMBAYARAN	RM 1,726.71 949.59 42.00 65.52 884.54 10.00 894.54
CONTACT NO. / TALIAN UNTUK TELEFON : NO. (NEW) / (OLD) : No. (BARU) / (LAMAR) NATIONALITY : KEWARGAAN BUSINESS / PROFESSION : PEKERJAAN BUSINESS REGN NO. : PENDAFTARAN SYARIKAT	0197320031 750622-01-5702 MALAYSIA HOMEMAKER/HOUSEWIFE	AGE / UMUR : 49	

VEHICLE REGISTRATION NO. No. PENDAFTARAN KENDERAAN	MAKE MODEL & TYPE OF BODY MODEL BUATAN DAN JENIS BADAN	H.P/CUBIC CAPACITY/ TONNAGE OR WATT H.P/KEUPAYAAN ENJIN/ TAN ATAU WATT	YEAR OF MANUFACTURE TAHUN DIPERBUAT	SEATING CAPACITY INCLUDING DRIVER KAPASITI TEMPAT DUDUK TERMASUK PEMANDU	INSURED'S ESTIMATE OF VALUE INCLUDING ACCESSORIES & SPARE PARTS(RM) NILAI ANGGARAN ANDA TERMASUK AKSESORI & ALAT GANTIAN(RM)
JSA9700	TOYOTA VIOS SALOON	1496.0 CC	2017	5	47,000.00

ENGINE/MOTOR NO. : ENJIN/MOTOR	2NR0N09048	CHASSIS NO. : NO. CASIS	PN153SYF103010443
MED DRIVERS : MAMPU YANG DIAMAKAN	ALL DRIVERS		
RE PURCHASE OWNERS : MILIK SEWA BELI	00002291 TOYOTA CAPITAL MALAYSIA SDN BHD	TYPE OF COVER : JENIS PERLINDUNGAN	COMPREHENSIVE
REGISTRATION RD NO. : KAD PENDAFTARAN	NA	EXCESS : LEBIHAN	0.00

SUBJECT OTHERWISE TO TERMS, EXCEPTIONS AND CONDITIONS OF THE POLICY AND THE ENDORSEMENTS/WARRANTY/MEMORANDUM AS NUMBERED
LOW:

LAINNYA TERTAKLUK KEPADA TERMA, PENGECUALIAN DAN SYARAT-SYARAT POLISI INI DAN PENGENDORSAN/WARRANTY/MEMORANDUM SEPERTI TERSEBUT DIBAWAH:

Code	Description	(RM)	(RM)
		Value	Premium
D518	WAIVER OF COMPULSORY EXCESS FOR UNNAMED DRIVER(NON-TARIFF)	-	15.00
D527	UNLIMITED TOWING (NON-TARIFF)	-	27.00
E015	HIRE PURCHASE	-	-
E87	AGREED VALUE ENDORSEMENT	-	-

Geographical Area: Malaysia, Republic of Singapore and Negara Brunei Darussalam.

Wilayah Geografi: Malaysia, Republik Singapura dan Negara Brunei Darussalam.

Limitation as to use / Authorised Driver: As described in the Certificate of Insurance.

Pada Penggunaan / Pemandu yang diberi kuasa: Seperti yang tercatat dalam Sijil Insuran.



TOKIO MARINE
INSURANCE GROUP

TOKIO MARINE INSURANS (MALAYSIA) BERHAD

198601000381 (149520-U)

ROAD TRANSPORT ACT 1987 (MALAYSIA) MOTOR VEHICLE (THIRD PARTY RISKS)
RULES 1959 MALAYSIA MOTOR VEHICLES (THIRD PARTY RISKS & COMPENSATION)
ACT (CAP 189) REPUBLIC OF SINGAPORE MOTOR VEHICLES (THIRD PARTY RISKS & COMPENSATION)
RULES 1960 (REPUBLIC OF SINGAPORE) MOTOR VEHICLES INSURANCE THIRD PARTY
RISKS ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

CERTIFICATE OF INSURANCE SIJIL INSURANS

MX1

CERTIFICATE NO. / POLICY NO. :
NO SIJIL / NO POLISI

V6207844 (VS163912)

1. Index Mark and Registration Number of Vehicle :
Tanda Indeks dan No. Pendaftaran Kenderaan

JSA9700

2. Name of Policyholder :
Nama Pemegang Polisi

SAROJA A/P BONGASAMY

3. Effective date of the Commencement of Insurance :
Tarikh Kuatkuasa Tempoh Insurans

01-04-2024

4. Date of Expiry of the Insurance :
Tarikh Tamat Tempoh Insurans

31-03-2025

5. Person or Classes of Persons entitled to drive :
Orang atau kelas orang yang layak memandu

a) The Policyholder.

b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. Dengan syarat orang tersebut dibenarkan memandu menurut undang-undang perlesenan atau undang-undang atau peraturan untuk memandu Kenderaan Bermotor tersebut atau telah dibenarkan dan tidak dilucutkan kelayakannya atas perintah Mahkamah atau atas sebab mana-mana enakman atau peraturan daripada memandu Kenderaan Bermotor.

3. Limitations as to use / Had-had Penggunaan:

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- (1) Use for hire or reward.
- (2) Use for racing pace-making reliability trial or speed-testing.
- (3) Use for the carriage of goods other than samples in connection with any trade or business.
- (4) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading.

Pengehadan dijadikan tidak berkuat kuasa oleh Seksyen 95 Akta Pengangkutan Jalan 1987 (Malaysia) atau Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam tidak termasuk di bawah tajuk ini.

We certify that this covering note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Saya/Kami dengan ini mengesahkan bahawa Nota Perlindungan ini yang diperuntukan mengikut Bahagian IV Akta Pengangkutan Jalan 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicle Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

ISSUING DATE / TARIKH DIKELUARKAN :
AGENCY NO. / NO. AGENCY :

29-03-2024

JB-00016810 / SHOWA AUTO TRADE (M) SDN BHD

ISSUED BY / DIKELUARKAN OLEH:

SHOWA AUTO TRADE (M)
SDN BHD

Chief Executive Officer / Ketua Pegawai Eksekutif
TOKIO MARINE INSURANS (MALAYSIA) BERHAD

JSA 9700

Rear Bootlid
 " " hinge x2 @ 97.40
 " " outer midj
 " " lock
 " " Stricker
 " " logo
 " " Vias logo
 " " X logo
 " " marker strip
 Taillamp assy x2 @ 445.80
 " panel
 " " garnish

M @ 852.40 —
 R @ 194.80 X
 CM/nd @ 201.40 —
 M @ 198.60 —
 R @ 29.90 X
 M @ 57.00 —
 MC @ 61.00 —
 M @ 57.00 —
 nd/di @ 166.40 5081n 83.205n
 CM @ 891.60 —
 M @ 710.20 —
 M/di @ 198.70 —

Rear bumper assy
 " " retain x2 @ 131.90
 " " reinforcement
 " " reverse sensor
 " " clips
 Rear Bumper RH

APC @ 565.00 —
 CM @ 263.80 —
 R @ 322.30 X
 S @ 300.005n X
 M @ 60.005n —
 R @ 894.80 X

258

Rear no plate
 " windscreen Sealant

CM @ 50.00 255n
 M @ 40.00 X

Labour

1. To dismantle / renew accident damaged portion. To panel beat, straighten and align replacement parts. \$ 1200.00 80d
2. To check wiring \$ 40.00 20d
3. To rust proof affected portion after repair. \$ 100.00 60d

4. To remove & refix rear windscreen nu \$ 150.00 X
5. To remove & refix interior trim, garnish & etc. \$ 150.00 80%
6. Supply spray paint materials & respray affected areas. \$ 1500.00 1000%
7. Remove & refix rear reverse sensor \$ 80.00 50%—

Not withstanding
 11 By \$ 4100/-
 Pursuing After Party

9334-90

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days

JSA 9700

Rear Bootlid

" " hinge x2 @ 97.40
 " " outer midj
 " " lock? clear photos 0075
 " " Stricker
 " " logo
 " " Vios logo
 " " X logo
 " " weather strip? photos 0074

Tailamp assy x2 @ 445.80

" panel
 " garnish

R 852.40 ✓
 R 8194.80 X
 CM/nd 201.40 ✓
 R 198.60 ✓?
 R 29.90 X
 R 57.00 ✓
 R 61.00 ✓
 R 57.00 ✓
 R 166.40 50612 83.2012
 CM 891.60 ✓
 R 710.20 ✓
 R 198.70 ✓

Rear bumper assy

" " retainer x2 @ 131.80 clear photos 0074
 " " reinforcement
 " " reverse sensor
 " " clips

Rear Bumper RH

R 565.00 ✓
 CM 263.80 ✓?
 R 322.30 X
 R 300.00 X
 R 60.00 X 20
 R 894.80 X

258

Rear No plate

" windscreen Sealant

CM 50.00 255235
 R 40.00 X

Labour

1. To dismantle / renew accident damaged portion. To panel beat, straighten and align replacement parts. \$ 1200.00 80d ✓
2. To check wiring \$ 40.00 20d ✓
3. To rust proof affected portion after repair. \$ 100.00 60d ✓

4. To remove & refix rear windscreen nu £150.00 X
5. To remove & refit interior trim, garnish & etc. £150.00 80/✓
6. Supply spray paint materials & respray affected areas. £1500.00 1000/✓
7. Remove & refix rear reverse sensor £80.00 50/✓

Not Withheld
 11/12/12 £4100/✓
 Pursuing After Party

933490

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

6 days

THIAM HENG HUAT PTE LTD

176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721
Phone 8263 6295 (Steven) Fax 6266 2881

ESTIMATE

DATE 10-Oct-24
Vehicle No JSA9700
Make/Model Toyota Vios
Date of Accident 16-Sep-24

Bill To:
Saroja A/P Bongasamy
c/o 176 Sin Ming Drive
#05-14 Sin Ming AutoCare
Singapore 575721

NO	DESCRIPTION	AMOUNT
LIST ITEMS		
1	Rear bootlid BT	\$ 852.40
2	Rear bootlid hinge x 2 @97.40 R	194.80 X
3	Rear bootlid outer moulding cra/cld	201.40
4	Rear bootlid lock dd SVC	198.60
5	Rear bootlid striker R	29.90 X
6	Rear bootlid logo nrc	57.00
7	Rear bootlid VIOS logo nrc	61.00
8	Rear bootlid X logo nrc	57.00
9	Rear bootlid weatherstrip scg dd / dist nn	166.40
10	Taillamp assy x 2 @445.80 CRA	891.60
11	Taillamp panel BT	710.20
12	Taillamp panel garnish mtg dist	198.70
13	Rear bumper assy Buc	565.00
14	Rear bumper retainer x 2 CRA	263.80
15	Rear bumper reinforcement R	322.30 X
16	Rear fender RH R	894.80 X
Less 25%		5,664.90
		1,416.23
S/NETT ITEMS		\$ 4,248.67
1	Rear bumper reverse sensor SVC	300.00 X
2	Rear bumper clips nrc	60.00 20
3	Rear number plate CRA	50.00 35
4	Rear windscreen sealant nn	40.00
LABOUR & MISC		
1	To dismantle/renew accident damaged portion. To panel beat, straighten and align replacement parts	1,200.00 800
2	To check wiring	40.00 20
3	To rust proof affected portion after repair	100.00 60
4	To remove & refit rear windscreen	150.00 X nn
5	To remove & refit interior trim, garnish & etc	150.00 80
6	Supply spray paint materials & respay affected areas	1,500.00 1000
7	Remove & refix rear reverse sensor	80.00 50
TOTAL		\$ 7,918.67

THIAM HENG HUAT PTE LTD



LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: