



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24090347/Kvh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	01/11/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6820E	Veh. Inspected	JSA 9700
Policy No.	-	Coverage	0
Claim No.	BVS24/0666	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	18/09/2024

2. Vehicle Details

Make & Model	TOYOTA VIOS (A)	C.C	1496
Engine No.	2NR0N09048	Year of Reg.	26/02/2017
Chassis No.	PM153SYF103010443	Colour	WHITE
Odometer	102113 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	TOYO	9
L/H Front Tyre	185/60R15	TOYO	9
R/H Rear Tyre	185/60R15	TOYO	9
L/H Rear Tyre	185/60R15	TOYO	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/09/2024	Inspection Date	19/09/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days