



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0483/2024/KS
DATE : 25-Jun-24
WIP : 20045

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR JAIN SONAM
ADDRESS : 37 AMBER GARDENS
#21-15
SINGAPORE 439969
TELEPHONE : HP +65 96523002
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800017636-06
VEHICLE NO : **SLW 5710 M**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 22/2/2018
ENGINE NO : CVK 049165
CHASSIS NO : WAUZZZF4XJA063644
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jun-24
PLACE OF ACCIDENT : AMBERS GARDENS, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408889

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAN@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLW 5710 M.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	S/N \$ 480.00	/
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$ 350.00	?
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT RE- ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	\$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET	\$ 1,900.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		\$ 6,122.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 5710 M.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de</i>	1	\$	2,670.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1		TBC
3	FRONT BUMPER SECURING STRIP <i>X</i>	2	\$	90.00
4	FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$	245.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	1	\$	286.00
6	FRONT BUMPER AIR GUIDE - LH / RH <i>X</i>	2	\$	160.00
7	RADIATOR GRILLE <i>cm</i>	1	\$	1,613.00
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	1	\$	169.00
9	FRONT PARKING AID SENSOR <i>?</i>	2	\$	572.00
10	FRONT PARKING AID SENSOR SEAL RING <i>cm</i>	4	\$	11.00
11	FRONT BUMPER TOP COVER <i>X</i>	1	\$	160.00
12	FRONT FOAM FILLER PIECE <i>?</i>	1	\$	156.00
13	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	1,033.00
14	OUTSIDE TEMP SENSOR BRACKET <i>?</i>	1	\$	37.00
15	LOCK CARRIER BRACKET <i>?</i>	1	\$	173.00
16	"CAUTION" STICKER <i>X</i>	1	\$	25.00
17	"A/C" STICKER <i>X</i>	1	\$	10.00
18	LED HEADLIGHT - LH <i>?</i>	1	\$	9,325.00
19	LED HEADLIGHT SPACER - LH <i>?</i>	3	\$	150.00
20	RADIATOR AIR GUIDE - LH / RH OUTER <i>?</i>	2	\$	54.00
SUB TOTAL SPARE PARTS		:	\$	16,939.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLW 5710 M.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER - LH X	1	\$	252.00
22	LIFT CYLINDER BRACKET - LH X	1	\$	8.00
23	BONNET repair	1	\$	3,470.00
24	BONNET ATTACHMENT X	1	\$	460.00
25	BONNET IMPACT PROTECTION - CENTER cm	1	\$	36.00
26	BONNET IMPACT PROTECTION - LH / RH X	2	\$	72.00
27	FRONT FENDER LEDGE COVER - LH SHORT ?	1	\$	29.00
28	FRONT FENDER LEDGE COVER - LH LONG X	1	\$	39.00
29	BONNET STRIKER - LH / RH X	2	\$	126.00
30	RADIATOR AIR GUIDE - LH / RH ?	2	\$	80.00
31	RADIATOR AIR GUIDE - LH / RH ?	2	\$	80.00
32	RADIATOR AIR GUIDE - UPPER X	1	\$	27.00
33	RADIATOR AIR GUIDE - LOWER X	1	\$	40.00
34	FRONT NO PLATE X	S/N	\$	60.00
35	SUNDRIES		\$	500.00
TOTAL SPARE PARTS			:	\$ 22,218.00
TOTAL LABOUR CHARGES			:	\$ 5,122.00
GRAND TOTAL			:	\$ 27,340.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Rosm - Hp 90010068*
SURVEYED DATE : *25/06/24*
AUTHORISED DATE : *4 days*
EXCESS COST : *EXCESS-TBA*
LIABILITY : *Repair*
REMARKS : *Res 54 mil*

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT