

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 I/P: 9742 6003

Not Authorized
L/Sing & J.850/p
Recovery After Paint
9 days

REPAIR ESTIMATE SMH3399J

No.	Qty	Nett Items			
1	1	Front bumper	76270	\$ CM	947.40 ✓
2	1	Front bumper grille		\$ Sn	385.00 X
3	1	Front bumper LH fog lamp cover		\$ Sn	45.00 X
4	1	Front bumper LH fog lamp		\$ Sn	327.00 X
5	1	Front bumper lower black skirting		\$ Dir	429.00 ✓
6	1	Front bumper LH side retainer		\$ CM	25.00 ✓
7	1	Front bumper inner reinforcement		\$ R	321.00 X
8	1 set	Front bumper clips		\$ In	50.00 ✓
9	1	LH headlamp	1917	CM	2,050.00 ✓
10	1	LH headlamp lower bracket		\$ R	35.00 X
11	1	Front LH fender		\$ R	444.70 ✓
12	1	Front LH fender lower black garnish		\$ R	178.00 ✓
13	1 set	Front LH fender lower black garnish clips		\$ In	40.00 ✓
14	1	Front LH fender under shield		\$ Dir	129.00 ✓
15	1 set	Front fender under shield clips		\$ In	30.00 ✓
16	1	Front LH wheel house panel		\$ R	670.50 X
17	1	Front LH wheel house extension		\$ R	280.00 X
18	1	Front LH side mirror body		\$ Dir	623.00 ✓
19	1	Front LH side mirror cover		\$ R	84.40 X
20	1	Front LH door		\$ R	950.00 ✓
21	2	Front LH door hinge (Top & bottom)		\$ R	116.40 X
22	1	Front LH door checker		\$ Sn	85.70 X
23	1	Front LH door weatherstrip		\$ Sn	87.40 X
24	1 set	Front LH door inner trim board clips		\$ In	50.00 X
25	2	Front sport rims LH/RH		\$ Dir	1,645.80 ✓
26	2	Front shock absorber LH/RH		\$ R	736.00 X
27	2	Front lower arm LH/RH		\$ Dir	933.00 X
28	2	Front knuckle arm LH/RH		\$ R	540.00 X
29	1	Front LH drive shaft		\$ R	1,018.70 X
30	1	Front stabilizer bar		\$ Sn	211.70 X
31	1	Front stabilizer bar LH link rod		\$ Sn	107.60 X
32	2	Front wheel hub LH/RH		\$ R	510.00 X
33	2	Front wheel bearing LH/RH		\$ In	300.00 X
			208	Total :	\$ 14,386.30

Special Nett Items

34	1	Front LH tyre		\$ Tn	220.00 509 In 110SN
----	---	---------------	--	-------	---------------------

Labour

1	Towing charges.	\$	80.00	60l
2	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,600.00	70d
3	To putty and spray Spray Paintings charges.	\$	1,200.00	860l
4	To check wirings and lightings.	\$	40.00	2d
5	To remove, refit front door fittings.	\$	80.00	60l
6	To remove, refix both front under carriages damage parts.	\$	280.00	24d

7	To remove, refit engine & gearbox assy, to facilitate repair	\$	ⁿⁿ 350.00	X
8	To conduct computerise wheel alignment test.	\$	100.00	601
9	To supply and apply anti rust treatment	\$	80.00	601
Total :		\$	<u>3,810.00</u>	

Total Parts and Labour : \$ 18,416.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

19.09.2024

SUPPLEMENTARY REPAIR ESTIMATE FOR Honda Vezel - SMH 3399 J

List Items
1 pc. LH Rocker Panel garnish
1 pc. Front bumper spoiler

od/wr
\$ 320.00 ✓
cm 84.90 ✓
\$ 404.90
Less 20% 80.98
\$ 323.92 \$ 323.92

Special Nett Items
1 pc. Front RH tyre
1 set. Front LH mud flap

1105N *cm* \$ 220.00 ✓
5061N *oil* \$ 280.00 ✓
TOTAL **\$ 823.92**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Factory Japan 2022.0.1 : Honda : Vezel : RU1 : except 18" Wheel
 Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-2°24'	-2°24'	-1°00' 1°00'
5°27'	5°27'	4°00' 6°00'
-0°20'	-0°20'	-0°08' 0°08'
15°21'	15°21'	11°30' 13°30'
12°57'	12°57'	10°30' 14°30'

Front : Right

Actual	Before	Specified Range
-1°15'	-1°15'	-1°00' 1°00'
5°50'	5°50'	4°00' 6°00'
-0°22'	-0°21'	-0°08' 0°08'
14°42'	14°42'	11°30' 13°30'
13°27'	13°27'	10°30' 14°30'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-1°08'	-1°09'	-0°45' 0°45'
-0°24'	-0°24'	
0°39'	0°39'	
-0°42'	-0°42'	-0°15' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°49'	-1°49'	-2°30' -0°30'
0°08'	0°08'	0°00' 0°15'

Rear : Right

Actual	Before	Specified Range
-1°37'	-1°37'	-2°30' -0°30'
0°01'	0°01'	0°00' 0°15'

Camber
 Toe

Rear

Cross Camber
 Total Toe
 Thrust Angle
 Axle Offset

Actual	Before	Specified Range
-0°12'	-0°12'	-0°45' 0°45'
0°09'	0°10'	0°00' 0°31'
0°03'	0°03'	
0mm	0mm	