



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|---|------------|
| UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909 ATTN: JOEY TAY | | | Ref: CS/UOI24090350/Rvp3e2(N) Date: 11/03/2025 Code: UOI2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SJU 7055S | Veh. Inspected | SCR 1188E |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | M13D00012410 | Excess (\$) | 0.00 |
| | Assign From | JOEY TAY | Assign Date | 18/09/2024 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | B.M.W. 523I 2.5 | c.c | 2497 |
| | Engine No. | HIDDEN | Year of Reg. | 2011 |
| | Chassis No. | WBAFP32080C867260 | Colour | BLACK |
| | Odometer | 208903 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | FAIR | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 245/45 R18 | MICHELIN | 6 mm |
| | L/H Front Tyre | 245/45 R18 | MICHELIN | 6 mm |
| | R/H Rear Tyre | 245/45 R18 | MICHELIN | 6 mm |
| | L/H Rear Tyre | 245/45 R18 | MICHELIN | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 15/09/2024 | Inspection Date | 19/09/2024 |
| | Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 7 Working Days | |