

REF:

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFH 3609L Yr Regn: 2017, Feb.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C200 C.O. 1991Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 127566 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2050422R 225138Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/35R19R: 245/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mmL/Bal. 06 mmD.O.A. _____ D.O.I. 19/09/24Survey held at CAS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / ST CapCOE ExpiryEstimate given during: Yes (✓)
1st Survey: No ()MV: 76KPV: 39.5KNett: 36.5K

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Main Form / L.P. / C.

☐: Preli. Report☐: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$☐: Interview (\$☐: Tech. Inve (\$

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

M/S : MS FIRST CAPITAL INSURANCE LIMITED
(MOTOR CLAIM DEPARTMENT)

Email motor_claims@msfirstcapital.com.sg

Parts - (%)	
SN:	
Labour	
Lump sum	
ERV	

Vehicle No: SFH3609L

Date:

Vehicle Model: MERCEDES C200

Reg. Date:

28.02.2017

Chassis No: WDD2050422R225138

D.O.A:

16.09.2024

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Bonnet <i>Repr</i>	1	\$ 2,300.00	\$ 2,300.00	<i>+</i>
2	Bonnet Lock LH <i>Repr</i>	1	\$ 110.00	\$ 110.00	<i>+</i>
3	Bonnet Active Hinge LH/RH <i>3 pieces</i>	2	\$ 260.00	\$ 520.00	<i>+</i>
4	Bonnet Active Hinge Actuator LH/RH <i>2</i>	2	\$ 245.00	\$ 490.00	<i>+</i> ?
5	Wiper Arm RH <i>Repr</i>	1	\$ 290.00	\$ 290.00	<i>+</i>
6	Front Fender LH <i>Dented</i>	1	\$ 1,150.00	\$ 1,150.00	<i>✓</i>
7	Front Fender Cowling LH - Front <i>Dented</i>	1	\$ 180.00	\$ 180.00	<i>✓</i>
8	Headlamp Bulb Replacement Cover LH <i>Repr</i>	1	\$ 85.00	\$ 85.00	<i>+</i>
9	Front Fender Emblem LH - Turbo AMG <i>Repr</i>	1	\$ 50.00	\$ 50.00	<i>✓</i>
10	Headlamp LH <i>Cracked</i>	1	\$ 3,600.00	\$ 3,600.00	<i>✓</i>
11	Headlamp Control Module LH <i>Repr</i>	1	\$ 900.00	\$ 900.00	<i>+</i>
12	Front Bumper <i>Distorted</i>	1	\$ 1,680.00	\$ 1,680.00	
13	Front Bumper Side Retainer Garnish LH <i>2 Distorted</i>	1	\$ 115.00	\$ 115.00	<i>✓</i>
14	Front Bumper Side Retainer LH - Fender Side	1	\$ 25.00	\$ 25.00	<i>✓</i>
15	Front Bumper Upper Side Bracket LH <i>Distorted</i>	1	\$ 95.00	\$ 95.00	<i>✓</i>
16	Front Radiator Grille <i>?</i>	1	\$ 220.00	\$ 220.00	<i>?</i>
17	Front Bumper Center Grille <i>Repr</i>	1	\$ 190.00	\$ 190.00	<i>+</i>
18	Front Bumper Center Lower Grille <i>Repr</i>	1	\$ 120.00	\$ 120.00	<i>+</i>
19	Front Bumper Side Lower Grille LH <i>Dented</i>	1	\$ 95.00	\$ 95.00	<i>✓</i>
20	Front Bumper Sensor LH <i>Dented</i>	3	\$ 280.00	\$ 840.00	<i>✓</i>
21	Front Reinforcement <i>Repr</i>	1	\$ 560.00	\$ 560.00	<i>+</i>
22	Support Panel <i>Repr</i>	1	\$ 860.00	\$ 860.00	<i>+</i>

C/F \$ 14,475.00



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883
Company & GST Registration No : 201828067M

VEHICLE INSPECTION ESTIMATE

B/F \$ 14,475.00

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
23	Engine Under Cover ?	1	\$ 280.00	\$ 280.00	?
24	Front Lower Arm LH ?	1	\$ 860.00	\$ 860.00	?
25	Front Thrust Arm LH ?	1	\$ 670.00	\$ 670.00	?
26	Front Wheel Bearing W Hub LH ?	1	\$ 640.00	\$ 640.00	?
27	Front Brake Caliper Hose LH new ?	1	\$ 175.00	\$ 175.00	+ ?
28	Front Shock Absorber LH new	1	\$ 720.00	\$ 720.00	+

Total For List Items: \$ 17,820.00

Less Spare Parts Discount (10%): \$ 1,782.00

Total: \$ 16,038.00

SPECIAL NETT ITEMS

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	Bonnet Insulator Clips 1set new	1	\$ 30.00	\$ 30.00	+
2	Front Number Plate W Casing new	1	\$ 60.00	\$ 60.00	+
3	Front Bumper Clips 1set new	1	\$ 30.00	\$ 30.00	✓
4	Front Bumper Rivet 1set new	1	\$ 30.00	\$ 30.00	-
5	Front Bumper Eyesbow 1set missing	1	\$ 260.00	\$ 260.00	2w
6	Brake Fluid Per/L new	2	\$ 12.00	\$ 24.00	+
7	Front Rim LH new	1	\$ 2,400.00	\$ 2,400.00	1600
8	Front Tyre LH - Michelin 245/35ZR19 new	1	\$ 430.00	\$ 430.00	+

Total For S/N Items: \$ 3,264.00

LABOUR

S/No.	Item Description	Qty	Price	Total Cost	Surveyor Use
1	To panel beat/straighten/realign accident affected areas	1	\$ 1,000.00	\$ 1,000.00	500
2	To spray paint on affected areas	1	\$ 1,200.00	\$ 1,200.00	7w
3	To tuff coat on affected areas	1	\$ 60.00	\$ 60.00	30
4	To conduct wiring check and repair	1	\$ 60.00	\$ 60.00	30
5	To reprogram/realign headlamp and focus	1	\$ 150.00	\$ 150.00	+
6	To dismantle, replace and/or ac compressor, air con condenser & refill air con gas	1	\$ 120.00	\$ 120.00	+
7	To dismantle, replace and/or repair radiator and pressure test	1	\$ 120.00	\$ 120.00	+
8	To remove/refix front sensor and distance setting	1	\$ 60.00	\$ 60.00	50
9	To replace front undercarriage parts	1	\$ 250.00	\$ 250.00	7
10	To conduct computerised wheel alignment	1	\$ 120.00	\$ 120.00	80

Total For Labour: \$ 3,740.00

Grand Total: \$ 23,042.00

Adrian L
1/2 19/09/24
00 Days