

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Richard Ang Wei Guang

Date: 14 Jan 2025

Preliminary Advice

Vehicle No	: SNL2534J	Accident Date	: 18/09/2024
Make	: KIA CERATO	Policy No.	: 1003048537
Assignment Date	: 19/09/2024	Excess	: S\$500.00
Date of Inspection	: 19/09/2024	Est. Duration of Repair	: 4
Inspection At	: AUTOBACS CAR CARE (SINGAPORE) PTE LTD (HQ) 8 KAKI BUKIT AVE.4, #08-45/46 PREMIER@KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,637.55 (inclusive supp \$2,132.75)
Revised Amount	:S\$	6,215.21
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,215.21
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	26,655.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,345.00

Remarks

- () The vehicle is economical for repair
() The vehicle is not economical for repair
(x) Part-by-Part repair
() Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.
Kindly approve on supplementary.