

(08/11/13) wef

ASS. REC BY: Marcus

REF:

CS/MSG 24090354/Unp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNL 2534Jat Workshop m/s Autobacs

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: € 64k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: L 14 826 655Veh No: SNL 2534J Yr Regn: 13/05/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: KIA Cerato 1.6A c.c 1591Colour: Red A/C: Insured / Std / NI / NASp. Reading: 67470 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFS416MK5027628

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 5 mm Rear 5 mmR/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 18/09/24 D.O.I. 19/9/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/1/28
 NO 2nd hand parts repairer want p/p repair
 tyre in good condition, brake in order
 P45127 cost plus 5%
 p/p 8.6215.21 inspect MR Sam
 (Red, \$ 3422.34, 35%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 483G

Vehicle Details

Vehicle No.: SNL2534J
Vehicle to be Exported: No
Intended Deregistration Date: 19 Sep 2024
Vehicle Make: KIA
Vehicle Model: CERATO 1.6(A) SUNROOF
Primary Colour: Red
Manufacturing Year: 2018
Engine No.: G4FGJH716130
Chassis No.: KNAF5416MK5027628
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$18,727.00
Original Registration Date: 13 May 2019
First Registration Date: 13 May 2019
Transfer Count: 1
Actual ARF Paid: \$18,727.00 9363

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 May 2029
PARF Rebate Amount: \$13,108.00

Intended COE Rebate Details

COE Expiry Date: 12 May 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$29,159.00
COE Rebate Amount: \$13,547.00
Total Rebate Amount: \$26,655.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 19 Sep 2024

OK

Autobacs Car Care Singapore Pte Ltd
8 Kaki Bukit Ave 4 #08-45,
Premier@ Kaki Bukit, Singapore
415875

Insurer Reference:
Repairer Reference: 072830
Date calculated: 18/09/2024 4:23 PM

Full Report
Registration: SNL2534J
Printed: 18/09/2024 4:24 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	ST SIM	Currency:	SGD
Claim Reference:		Date of Incident:	18/09/24
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	CERATO (YD)
Sub Model:	S
Model Sheet Number:	28 98 13
Registration:	SNL2534J
VIN number:	KNAF5416MK5027628
Odometer:	

Model Specs

LED HEADLAMP

not Autobacs
in
merch
Excess \$500
Warranty setu party
4 days
11P \$6215.21
90096608

Autobacs Consultant's hence notify
that the price of the following:
• Temporary vehicle hire/repair
• The cost of temporary vehicle hire/repair
• All other prices are subject to confirmation
• That any survey is on a "Will do" basis
• No "No" and modification(s) is allowed
• Supplementary item(s) must be returned
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5127

Vehicle Condition

Vehicle Status

Pre-Accident Damage:


Date of Inspection:

Damage Areas

All

☐

Underbody

☐

Tyres Condition

Tyre Brand	Tread (Left Middle), mm	Tread (Left Outer), mm	Tread (Left Inner), mm	Tread (Right Inner), mm	Tread (Right Outer), mm	Tread (Right Middle), mm	Condition
------------	-------------------------	------------------------	------------------------	-------------------------	-------------------------	--------------------------	-----------

Spare Tyre Brand

Tread (Spare), mm

Labour

Code	Description	Time Base 10 WU/h	Price = 52.50 SGD/h	
			WU	Price SGD
86512R00)	RENEW FRONT BUMPER (BUMPER REMOVED) INCLUDES: GRILLE AND REQUIRED ATTACHED PARTS R + R. ATTACHED PARTS ASSEMBLE IF NECESS RENEW.		5.0	26.25
86530R00)	R + R FRONT BUMPER SUPPORT		3.0	15.75
66400R00)	RENEW BONNET INCLUDES: R + R BONNET AND NECESSARY ATTACHED PARTS, RENEW ATTACHED PARTS IF NECESSARY		6.0	31.50
66300R0B	R + R BOTH WINGS FR INCLUDES: R + R BOTH HEADLAMP, BOTH WHEELHOUSES FR, BUMPER FR AND REQUIRED ATTACHED PARTS. DOES NOT INCLUDE: ADJUST HEADLAMP		12.0	63.00
18600A00)	ADJUST HEADLAMPS		3.0	15.75

repair support panel

30

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	2.90	29.0	152.25
Total of Labour			152.25

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description	WU Price SGD
	BONNET NEW PART PAINTING	15.0
	L/F WING NEW PART PAINTING	10.0
	R/F WING NEW PART PAINTING	10.0
	FRONT BUMPER NEW PART PAINT K1R	10.0
	FRT BUMPER TRIM CAP NEW PART PAINT K1R	3.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	37.08
0741	L/F WING NEW PART PAINTING	18.14
0742	R/F WING NEW PART PAINTING	18.14
0283	FRONT BUMPER NEW PART PAINT K1R	39.09
0299	FRT BUMPER TRIM CAP NEW PART PAINT K1R	0.35

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			48.0	
Preparation Main Work Metal		0.70	7.0	35.00
Preparation Comp. Work Plastic		0.30	3.0	15.00
Total	10 WU/h	5.80	58.0	290.00

Material Cost - Paint

	Price SGD
New Part Painting	73.36
New Part Painting - Plastic K1R	39.44
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	139.90

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	Price SGD
0471	BONNET	66400A7000	✓ Original	BUC	1,225.00 ✓
0283	FRONT BUMPER	86511A7000	✓ Original	RE	633.00 ✓
0315	FRONT IMPACT DAMPER	86520A7000	✓ Original	488	0.00 ✓
0293	FRONT SPOILER	86590A7000	Original	75	0.00 ✓
0340	FRT BUMPER SUPPORT	86530A7200	✓ Original	415	0.00 ✓
0299	FRT BUMPER TRIM CAP	86588A7000	Original	BUC	36.00 ✓
0291	FRT LWR BUMP GRILLE	86522A7000	Original	NA	0.00 ✓
0410	GRILLE	86350A7500	✓ Original	285	325.00 ✓
0431	GRILLE BADGE	863182T000	Original	CNE	48.00 ✓
0741	L/F WING	66311A7000	Original	R	363.00 ✓

Code	Description	Part Number	Part Source	Price SGD
0561	LEFT HEADLAMP ASSY	92101A7130	Original	1,800.00
0298	R/F BUMPER COVER	86564A7000	Original	0.00
0320	R/F UPP BUMPER BRKT	86518A7000	Original	0.00
0742	R/F WING	66321A7000	Original	363.00
0427	RAD GRILLE REINFORCEMENT	86356A7000	Original	0.00
0562	RIGHT HEADLAMP ASSY	92102A7130	Original	1,800.00
f: OEM Parts				0.00
n: Non-OEM Parts				6,593.00
u: Used parts				329.65
Savings				
Subtotal				6,593.00
Addition(+5.00%)				329.65
Total				6,922.65

Final Calculation

	SGD	SGD
Parts	6,593.00	
Addition(+5.00%)	329.65	
Total Parts		6,922.65
Labour Time Base 10 WU/h		
Total 29.0 WU X 52.50 SGD/h	152.25	
Total of Labour		152.25
Paint Work Time Base 10 WU/h		
Labour Cost 58.0 WU X 50.00 SGD/h	290.00	
Material Cost	139.90	
Total Paint Including Material		429.90
		7,504.80
Repair Cost Excludes GST		675.43
GST (+9.00%)		8,180.23
Repair Cost Included GST		

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Support panel grommet top

horn

CN \$75 ✓

hinge

Sub \$34x2 ✓

radiator top grommet

CN \$55 ✓

wiper grommet

CN \$245 ✓

Autobacs Car Care (Singapore) Pte Ltd (Co.Reg.No:201500047H)

8 Kaki Bukit Ave.4, #08-45/46 Premier@Kaki Bukit

Singapore 415875

Tel: 67895155 Email: st.sim@autobacs.com.sg

(SUPPLEMENTARY)INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	1003048537	Date of Loss:	18/09/2024
Vehicle Reg. No.:	SNL2534J	Driveable?	NO
Driver Age/Info:	32 / MALE / MANAGER	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH YAN HAO, SHAUN	Contact No:	+6597908366
Driver:	LOH YAN HAO, SHAUN		
Make/Model:	KIA CERATO, 1.6 SUNROOF (A)	Vehicle Reg. Date:	13/05/2019
Vehicle Colour:	RED		
Engine No:	G4FGJH716130	Chassis No:	KNAF5416MK5027628
Odometer:	67470 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	SNL2534J COLLIDED ONTO THE REAR OF SJE600Z.		
Present Location:	AUTOBACS CAR CARE (SINGAPORE) PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	2,132.75
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,132.75
+ GST 9.00% (S\$)	191.95
Nett Amount (S\$)	2,324.70
+ Previous Estimates (S\$)	7,635.23
Claim Total (S\$)	9,959.93

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jan 2025)
Parts: 143 KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Autobacs Car Care (Singapore) Pte Ltd/SNL2534J/10/01/2025 16:46
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*F/R fender	0.00	0.00	Repld *633.00 F X
2	1		*Bumper reinforcement	0.00	0.00	Repld *415.00 F X
3	1		*Front bumper energy foam	0.00	0.00	Repld *75.00 F X
4	1		*Front bumper RH side retainer	0.00	0.00	Repld *24.00 F X
5	1		*Horn Low	0.00	0.00	one *75.00 F
6	1		*Bonnet LH hinge	0.00	0.00	best *34.00 F
7	1		*Bonnet RH hinge	0.00	0.00	set *34.00 F
8	1		*Radiator grille garnish	0.00	0.00	repld *70.00 F X
9	1		*Horn high	0.00	0.00	an *75.00 F X
10	1		*Radiator top garnish	0.00	0.00	one *55.00 F
11	1		*Wiper garnish	0.00	0.00	cut *245.00 F
12	1		*Bumper side grille	0.00	0.00	Repld *220.00 F X
13	1		*front number plate	0	0.00	11 *50.00 FS X
14	1		*Front bumper clips	0	0.00	11 *30.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	2,035.00
+ Margin on L,N Items 5.00% (S\$)	97.75
Total Parts (S\$)	2,132.75

Autobacs Car Care (Singapore) Pte Ltd/SNL2534J/10/01/2025 16:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Autobacs Car Care (Singapore) Pte Ltd/SNL2534J/10/01/2025 16:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >