

ASS. REC. BY:

REF:

AG2/ CS/AGI24090356/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: GBG 6344H

Policy No.

Claims No. C10031699/JK

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNH 57042 Yr Regn: 09, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Vezel c.c. 1496

Colour:

M. Silver A/C: Insured / Std / NI / NA

Sp. Reading

248279 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / OIS / NIS / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2019

21.12.19 1900h. Coln

(red 6479.92, 77%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	813C
Vehicle Details	
Vehicle No.:	SNH5704L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	L15B4022326
Chassis No.:	RU11102323
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,399.00
Original Registration Date:	14 Sep 2015
First Registration Date:	14 Sep 2015
Transfer Count:	1
Actual ARF Paid:	\$8,399.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2025
PARF Rebate Amount:	\$4,199.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,498.00
COE Rebate Amount:	\$5,571.00
Total Rebate Amount:	\$9,770.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 19 Sep 2024

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

*Not Authorised
11 Sep @ 1900h
Repair After Paint
4 days*

19 SEPTEMBER 2024

Auto & General Insurance (Singapore) Pte
190 Clemenceau Ave
#03-01 Singapore Shopping Centre
Singapore 239924

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMX2032P

Accident involving vehicle no: SNH5704L/SMX2032P

DOA: 14/09/2024 at BRADDELL RD TOWARDS UPPER S'GOON RD

Dear officer in charge

Estimate cost of repair for vehicle no: SNH5704L

To supplied:

Description	Qty	Amount	
Rear bumper	<i>Per</i> 1	532.10	<i>X</i>
Rear bumper retainer	<i>Per</i> 2	59.20	<i>X</i>
Rear bumper reflector	<i>Per</i> 2	302.20	<i>X</i>
Tailgate	<i>Per</i> 1	997.70	<i>X</i>
Tailgate lock	1	96.20	<i>X</i>
Tailgate – Honda emblem	<i>NIP</i> <i>Per</i> 1	54.20	<i>X</i>
Tailgate – Vezel emblem	<i>Per</i> 1	49.80	<i>X</i>
Tailgate – H logo	<i>Per</i> 1	24.70	<i>X</i>
Tailgate reflector	<i>Per</i> 2	553.80	<i>X</i>
Tailgate center chrome	<i>Per</i> 1	241.50	<i>X</i>
Tailgate door board	<i>Per</i> 1	331.70	<i>X</i>
End panel	<i>Per</i> 1	362.70	<i>X</i>
End panel top garnish	<i>Per</i> 1	116.50	<i>X</i>
Tailamp	<i>Per</i> 2	964.80	<i>X</i>
Boot weatherstrip	<i>Per</i> 1	131.20	<i>X</i>
Luggage compartment trim box	<i>Per</i> 1	252.30	<i>X</i>
Spare tyre tool compartment	<i>Per</i> 1	172.80	<i>X</i>
Buzzer assy, smart	<i>Per</i> 1	86.10	<i>X</i>
Rear bumper corner panel	<i>Per</i> 2	332.60	<i>X</i>
Rear wheel garnish inner trim	<i>Per</i> 2	229.80	<i>X</i>
Spare tyre panel	<i>Per</i> 1	723.00	<i>X</i>
Bumper clip	<i>Per</i>	35.00	<i>X</i>

201

Parts		6,649.90
Parts less 20%		5,319.92

1. Reverse sensor	220.00	2005N-
2. Remove/reinstall rear windscreen glass	180.00	1201
3. Remove/reinstall inner garnish, rear speaker hood, rear interior cushion seat, roof lining Transfer rear wiper motor to new door	160.00	601
4. Remove damaged parts n attachment Cut n weld damaged panels To straighten rear chassis where necessary Repair/reshape damaged areas Replace/realign all parts into same position	1,200.00	400d
5. To spray paint	1,300.00	320d

	8,379.92	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: