

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128
Business Regn No: 269436/00J

Not Authorized
11 Sep & 1900h
Permy After Paint
4 days

19 SEPTEMBER 2024

Auto & General Insurance (Singapore) Pte
190 Clemenceau Ave
#03-01 Singapore Shopping Centre
Singapore 239924

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SMX2032P
Accident involving vehicle no: SNH5704L/SMX2032P
DOA: 14/09/2024 at BRADDELL RD TOWARDS UPPER S'GOON RD

Dear officer in charge
Estimate cost of repair for vehicle no: SNH5704L
To supplied:

Description	Qty	Amount	
Rear bumper	<i>Buc</i> 1	532.10	<i>X</i>
Rear bumper retainer	<i>sn</i> 2	59.20	<i>X</i>
Rear bumper reflector	<i>sn</i> 2	302.20	<i>X</i>
Tailgate	<i>sn</i> 1	997.70	<i>✓</i>
Tailgate lock	1	<i>n</i> 96.20	<i>X</i>
Tailgate - Honda emblem	<i>n/p</i> <i>sn</i> 1	54.20	<i>X</i>
Tailgate - Vezel emblem	<i>sn</i> 1	49.80	<i>X</i>
Tailgate - H logo	<i>sn</i> 1	24.70	<i>X</i>
Tailgate reflector	<i>sn</i> 2	553.80	<i>X</i>
Tailgate center chrome	<i>sn</i> 1	241.50	<i>X</i>
Tailgate door board	<i>sn</i> 1	331.70	<i>X</i>
End panel	<i>n</i> 1	362.70	<i>X</i>
End panel top garnish	<i>sn</i> 1	116.50	<i>X</i>
Tailamp	<i>sn</i> 2	964.80	<i>X</i>
Boot weatherstrip	<i>sn</i> 1	131.20	<i>X</i>
Luggage compartment trim box	<i>sn</i> 1	252.30	<i>X</i>
Spare tyre tool compartment	<i>sn</i> 1	172.80	<i>X</i>
Buzzer assy, smart	<i>sn</i> 1	86.10	<i>X</i>
Rear bumper corner panel	<i>sn</i> 2	332.60	<i>X</i>
Rear wheel garnish inner trim	<i>sn</i> 2	229.80	<i>X</i>
Spare tyre panel	<i>n</i> 1	723.00	<i>X</i>
Bumper clip	<i>sn</i>	35.00	<i>✓</i>
<i>201</i>			

Parts		6,649.90
Parts less 20%		5,319.92

1. Reverse sensor	220.00	2005N-
2. Remove/reinstall rear windscreen glass	180.00	1206
3. Remove/reinstall inner garnish, rear speaker hood, rear interior cushion seat, roof lining Transfer rear wiper motor to new door	160.00	601
4. Remove damaged parts n attachment Cut n weld damaged panels To straighten rear chassis where necessary Repair/reshape damaged areas Replace/realign all parts into same position	1,200.00	400
5. To spray paint	1,300.00	320
	8,379.92	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: