REF: FOZ/ ASS. REC. BY: Kenneth ASSIGNMENT SLE 9833/Ar Regn: 06, 16 From: Veh No: Estimated Cost: Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / OD /AP WS ITP RES / OD RES / EVA / INV / MY Truck / Trailer or To Inspect Vehicle No: Make: at Workshop m/s 5811 Colour M. P. white 9810 Sp.Reading T/Radio: Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: Claims No. Gen. Cond: good / Fair / Poor / Burnt Sum Insured: Excess: Steering: Inopaer / Jammed / Leaked / Burnt or (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or Make of Veh: Modi: NII / STRIM, / STD A/RIM or 215/60R16 Tyre Size: (Policy Condition) Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUM / repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Rear IDAC Accident Rport: Consistent?: Yes or No R/Bal R/Bal. GIA / PR Seen: Consistent?: Yes or No L/Bal. mm Est. Repairs: D.O.A. 10 1 ic Lum Sum: Survey held at CA / REV. / REP. / 24 HRS Des. of Damages : Frt / Rear 1 O/S / N/S / U/C / Rooftop or Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame() Body Structure affected due to collision. Date / Time Action / Instruction \$ 15,800k Max Time, File Pass to? : Prell. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: ine, File Return to? Transportation Add Fee: : Site Insp S - RS. SI Interview Format: Tech Invs (\$ 1. Others um / I.B.I: (S Weekend (\$. C. AL



Not Nothertal Ully 815,8001 Max Burny After Pains 23days

WORKSHOP

6453 4730

6457 1931

160 Sin Ming Drive #07-02 Sin Ming AutoCity Singapore 575722

enquiry@sh-motor.com

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K GST Reg. No.: M2-0076269-0

SH/2024/0121/TP 19/8/2024

M/s First Capital Insurance Ltd 36 Robinson Road #16-01

Kennera

96910663

City House Singapore 068877 23/8/24 File No: Date :

Estimated cost of repair for vehicle no:	SLE9833K	Hone	la Vezel		
Accident involving vehicle no:	SLE9833K	&	SHA7209U	On	10/6/2024
Description			Quantity		List Price
Front bumper			1		\$ 852.10
Front bumper lower lid			1		\$ Distim 381.00
Front bumper lower grille			1		s CM 189.00 -
Front bumper reinforcement			1		\$ Pg 385.00
Front bumper tow cover			1		\$ my 19.00 -
Front bumper side retainer @\$38.00			2		s CM 76.00 -
Front bumper fog lamp @\$327.70			2		s olsaii 655.40 L+
Front bumper fog lamp garnish @\$112	2.50		2		\$.4 225.00 4
Front bumper car plate moulding			1		s NJP 124.20 X
Main windscreen			1		s CM 1,335.00 -
Main windscreen moulding			1		s 180.00 -
Radar sensor			1		\$ 1,380.00 7
Front fender @\$596.80			2	NISR	s Ols R 1,193.60 L+
Front fender arch garnish @\$189.50			2		s Bu 379.00 L
Headlamp @\$1782.50			2		s CM/Av 3,565.00 ~
Headlamp lower bracket @\$89.50			2		s CM 89.50 -
Front radiator grille			1		s CM 421.00 -
Front radiator grille chrome moulding			1		\$ 121.00
Front radiator grille "Honda Logo" emb.	lem		1		
Horn	icin				
Bonnet			1		\$ 102.30
			1		s Bu 922.00 -
Bonnet hinge @\$48.90			2		s Dir 97.80 _
Bonnet lock			1		s R 122.00 -
Bonnet lock bracket			1		s cm 65.00 -
Bonnet insulator			1		s CM 122.90 L
Front support top panel			1		s Bu 711.00 -
Front support panel top garnish					A
Dash board assy			1		s hiy 185.50 c
			1		\$ 655.50
Air con condenser			1		s R _{1 750.20}
Radiator			1		\$ 1,298.00
Radiator bracket @\$25.00			2		A
Radiator side garnish @\$78.50					50.00
			2		s Cm 157.00
adiator fan motor assy			1		\$ 620,00
ear bumper			1		0
ear bumper side retainer @\$49.00					7 700.20
7			2		s CM 98.00

CM 98.00 L



		Co. Reg. No. : 19 GST Reg. No.: M	98701322K 12-0076269-0
•	2	\$	Sh 242.00 ¥
Rear bumper reflector @\$121.00	2	\$	Bn 431.00
Rear bumper side @\$215.50	1	\$	241.50 7
Rear bumper under cover	2		1,716.00
Rear fender @\$858.00	2	s Per	van 731.60
Rear fender inner trim @\$365.80	2	\$	Bn 344.00
Rear fender arc garnish @\$172.00	1	\$	By 998.30
Tail gate	2	\$	670.00 7
Tail gate reflector @\$335.00	1	\$	Def 321.00 -
Tail gate lock	1	\$	017 45.80
Tail gate lock catch	1	\$	Bu 198.50
Tail gate inner trim board	1	\$	5m 45.00 X
Tail gate inner board pocket handle	1	\$	268.00
Tail gate wiper motor	1	\$	Pulpi 298.00 56 ls
Tail gate weatherstrip	1	\$	Ma 58.00 —
Tail gate "Vezel" emblem	1	\$	ree 45.00
Tail gate "Honda Logo" emblem	1	\$	265.70
Tail gate outer garnish	2	\$	398.00 7
Tail gate shock asborber @\$199.00	2	\$	CM 970.00
Tail lamp @\$485.00	2	\$	R ₂ 330.00 -
Tail lamp panel @\$165.00	1	\$	3 623.00 \sim
Rear end panel	1	\$	nd 198.00
Rear end panel top garnish	1	\$	By 1,025.40 —
Rear floor panel		\$	Bu 241.50
Rear floor panel under cover	1		Od 269.90 —
Rear floor panel top cover	1	\$	770.00 7
Rear shock absorber @\$385.00	2	\$	1,650.00
Rear axle beam	1	\$	
Rear wheel bearing @\$263.50	2	\$	N~ 527.00 X
	1	\$	14 598.74
Rear exhaust silencer	2	\$	7 70.00 V
Rear exhaust silencer mounting @\$35.00		\$	33,218.04
	LESS 20%	\$	6,643.61
		\$	26,574.43
		4	20,01 1110
a control Mark			
Special Nett	1	\$	ON 70.00 4512
Front number plate & holder	set	\$	Mc 50.00 -
Front bumper clips	set	\$	Ma 40.00
Front fender inner shield clip		-	550.00 7
Front audio player	1	\$	
Bonnet insulator clips	set	\$	Ne 30.00
-	1	\$	320.00 7
Rear tyre rh	set	\$	Net 250.00 2000~
Reverse sensor		-	CM 70.00 451~
Rear number plate & holder	1	\$	
Rear bumper clips	set	\$	Ma 50.00 _
tom omiter sule			

6453 4730 6457 1931

WORKSHOP

enquiry@sh-motor.com

160 Sin Ming Drive #07-02 Sin Ming AutoCity Singapore 575722

S&H Motor Pte Ltd



6453 4730 6457 1931

enquiry@sh-motor.com

WORKSHOP

set

1

1

set

1

set

1

160 Sin Ming Drive #07-02 Sin Ming AutoCity Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K GST Reg. No.: M2-0076269-0

s	M	15.00	
S	M	40.00	OSM
\$	M	60.00 3	OIN
\$		400.00	
\$	nu	80.00	—
\$		150.00	
S	M	60.00	405 m
\$	M	60.00	-
\$		95.50	1

Labour

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.

Remove & refix dashboard and internal wiring

Remove & replace front radar sensor & conduct distance safety setting

Remove & refix aircon condenser and refill aircon gas

Remove & refix radiator, top up coolant & conduct pressure test

Remove & refix tailgate windscreen glass

Rear end panel top garnish clips

Rear end panel sealant

Rear floor panel sealant

Rear fender inner trim clips

Tail gate chrome trimming Tail gate windsceen sealant

Tail gate remote buzzer

Tailgate inner trim board clips

Rear reverse camera

Remove & refix/replace rear bumper reverse sensor & conduct distance safety setting

Remove & refix/replace rear reverse camera & conduct distance safety setting

Remove & refix/replace rear exhaust system

Transfer of existing tailgate mechanism to new tailgate

Remove & refix/replace rear undercarriage work

To conduct wheel alignment

To conduct rear chassis alignment

Conduct water leak test for rear portion associated repair work

Wiring /bulb checking/focusing

To putty & spray paint accident damaged parts and adjacent panels

	180000
\$	1,800.00
\$	300.00
\$	200.00 80
\$	120.00 100
\$	90.00 5 0l
\$	120.00
\$	70.00 Sol
\$	70.00 401
\$	90.00 601
\$	90.00 601
\$	350.00 20d
\$	100.00 601
\$	250.00
\$	40.00 201
S	100.00 401
\$	2,000.00
S	34,754.93

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged pan(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SS2X246C0008-01 / SME MOTOR PTE LTD ENTRY DATE & TIME: 12/06/2024 15:59 (SGT) SUBMITTED BY: CHRIS ANG VERSION: 2 (13/06/2024 10:00 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

12/06/2024 15:59 (SGT) Date of First Submission Both Policyholder and Actual Driver Reported by 10/06/2024 08:15 (SGT) Date of Accident **Exact Location of Accident** PIE, Singapore TOWARDS CHANGI Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **SLE9833K**

INSURED/POLICYHOLDER

Is company? NABILAH BINTE AHMAD Name Of Registered Owner S9001981C NRIC No MHAFIZHILA@GMAIL.COM **Email Address** (Phone) +65-97328528 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Honda Manufacturer Vezel Model Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private car Vehicle Category Auto Transmission 1500 CC

INSURANCE COMPANY

Income Insurance Limited Name of Insurance Company 5125252776-02 Policy Number / Cover Note Number

DRIVER

MUHD HAFIZ BIN KHAMIS Name of Driver S88501961 NRIC No 25/12/1988 Date Of Birth Outdoor Occupation

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesald.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to

- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposos")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers law firms, may are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents irms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signa Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)



vJun2022

Ke

, Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	
Owner ID:	Singapore NRIC
Vehicle Details	981C
Vehicle No.:	CLEODON
Vehicle to be Exported:	SLE9833K
Intended Deregistration Date:	No 22 Aug 2024
Vehicle Make:	22 Aug 2024
Vehicle Model:	HONDA VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	
Chassis No.:	L15B4028542
	RU11108539
Maximum Power Output:	96.0 kW (128 bhp) \$19,087.00
Open Market Value:	
Original Registration Date:	10 Jun 2016 10 Jun 2016
First Registration Date:	
Transfer Count:	1
Actual ARF Paid:	\$9,087.00
Intended PARF Rebate Details	Yes
PARF Eligibility:	09 Jun 2026
PARF Eligibility Expiry Date:	\$4,997.00
PARF Rebate Amount: Intended COE Rebate Details	φ4,777.00
	09 Jun 2026
COE Expiry Date:	A - Car up to 1600cc & 97kW (130bhp)
COE Category:	10
COE Period(Years):	\$47,889.00
QP Paid:	
COE Rebate Amount:	\$8,616.00
Total Rebate Amount:	\$13,613.00
Message	rrent COE (including unused COE from any lay-up period/s), if you renew your CO

The information contained herein is correct as at 22 Aug 2024