



6453 4730
6457 1931
enquiry@sh-motor.com

Not authorized
61 Rm @ 15,800 max
Resuming After Pains
23 days

Kenneth
96910663

23/8/24

WORKSHOP
160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd
Co. Reg. No.: 198701322K
GST Reg. No.: M2-0076269-0

SH/2024/0121/TP

19/8/2024

M/s First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

File No:

Date:

Estimated cost of repair for vehicle no:	SLE9833K	Honda Vezel	On	10/6/2024
Accident involving vehicle no:	SLE9833K	& SHA7209U	Quantity	List Price
Description				
			1	\$ B 852.10 ✓
Front bumper			1	\$ Di / cm 381.00 ✓
Front bumper lower lid			1	\$ CM 189.00 ✓
Front bumper lower grille			1	\$ B 385.00 ✓
Front bumper reinforcement			1	\$ m'y 19.00 ✓
Front bumper tow cover			1	\$ CM 76.00 ✓
Front bumper side retainer @\$38.00			2	\$ ol / m'y 655.40 ✓
Front bumper fog lamp @\$327.70			2	\$. 225.00 ✓
Front bumper fog lamp garnish @\$112.50			2	\$ N/A 124.20 X
Front bumper car plate moulding			1	\$ CM 1,335.00 ✓
Main windscreen			1	\$ m 180.00 ✓
Main windscreen moulding			1	\$ Su 1,380.00 X
Radar sensor			1	\$ ol / B 1,193.60 ✓
Front fender @\$596.80			2	\$ B 379.00 ✓
Front fender arch garnish @\$189.50			2	\$ CM / B 3,565.00 ✓
Headlamp @\$1782.50			2	\$ CM 89.50 ✓
Headlamp lower bracket @\$89.50			2	\$ CM 421.00 ✓
Front radiator grille			1	\$ m 385.00 ✓
Front radiator grille chrome moulding			1	\$ m 48.90 ✓
Front radiator grille "Honda Logo" emblem			1	\$ Su 102.30 X
Horn			1	\$ B 922.00 ✓
Bonnet			1	\$ Di 97.80 ✓
Bonnet hinge @\$48.90			2	\$ B 122.00 ✓
Bonnet lock			1	\$ CM 65.00 ✓
Bonnet lock bracket			1	\$ CM 122.90 ✓
Bonnet insulator			1	\$ B 711.00 ✓
Front support top panel			1	\$ m'y 185.50 ✓
Front support panel top garnish			1	\$ Su 655.50 X
Dash board assy			1	\$ B 750.20 ✓
Air con condenser			1	\$ Su 1,298.00 X
Radiator			1	\$ Di 50.00 ✓
Radiator bracket @\$25.00			2	\$ CM 157.00 ✓
Radiator side garnish @\$78.50			2	\$ Su 620.00 X
Radiator fan motor assy			1	\$ B 786.20 ✓
Rear bumper			1	\$ CM 98.00 ✓
Rear bumper side retainer @\$49.00			2	\$



6453 4730
6457 1931
enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K
GST Reg. No.: M2-0076269-0

Rear bumper reflector @\$121.00
Rear bumper side @\$215.50
Rear bumper under cover
Rear fender @\$858.00
Rear fender inner trim @\$365.80
Rear fender arc garnish @\$172.00
Tail gate
Tail gate reflector @\$335.00
Tail gate lock
Tail gate lock catch
Tail gate inner trim board
Tail gate inner board pocket handle
Tail gate wiper motor
Tail gate weatherstrip
Tail gate "Vezel" emblem
Tail gate "Honda Logo" emblem
Tail gate outer garnish
Tail gate shock absorber @\$199.00
Tail lamp @\$485.00
Tail lamp panel @\$165.00
Rear end panel
Rear end panel top garnish
Rear floor panel
Rear floor panel under cover
Rear floor panel top cover
Rear shock absorber @\$385.00
Rear axle beam
Rear wheel bearing @\$263.50
Rear exhaust silencer
Rear exhaust silencer mounting @\$35.00

2	\$	Sn	242.00	X
2	\$	Bu	431.00	✓
1	\$	Sn	241.50	X
2	\$	Bu 1B	1,716.00	✓
2	\$	Return	731.60	✓
2	\$	Bu	344.00	✓
1	\$	B	998.30	✓
2	\$	Sn	670.00	X
1	\$	Od	321.00	✓
1	\$	Oil	45.80	✓
1	\$	Bu	198.50	✓
1	\$	Sn	45.00	X
1	\$	Sn	268.00	X
1	\$	Palpi	298.00	501Sn
1	\$	Na	58.00	—
1	\$	Na	45.00	—
1	\$	Sn	265.70	✓
1	\$	Sn	398.00	X
2	\$	Com	970.00	✓
2	\$	B	330.00	✓
2	\$	B	623.00	✓
1	\$	Od	198.00	✓
1	\$	B	1,025.40	✓
1	\$	Bu	241.50	✓
1	\$	Od	269.90	✓
1	\$	Sn	770.00	X
2	\$	Sn	1,650.00	X
1	\$	Na	527.00	X
2	\$	B	598.74	✓
1	\$	Ta	70.00	✓
2	\$			
	\$		33,218.04	
	\$		6,643.61	
	\$		26,574.43	

LESS 20%

Special Nett

Front number plate & holder
Front bumper clips
Front fender inner shield clip
Front audio player
Bonnet insulator clips
Rear tyre rh
Reverse sensor
Rear number plate & holder
Rear bumper clips

1	\$	Od	70.00	451a
set	\$	Na	50.00	—
set	\$	Na	40.00	—
1	\$	Sn	550.00	X
set	\$	Na	30.00	✓
1	\$	Sn	320.00	X
set	\$	Od	250.00	2000
1	\$	Com	70.00	451
set	\$	Na	50.00	✓



☎ 6453 4730

☎ 6457 1931

✉ enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No. : 198701322K
GST Reg. No.: M2-0076269-0

Rear end panel top garnish clips
Rear end panel sealant
Rear floor panel sealant
Rear reverse camera
Rear fender inner trim clips
Tail gate chrome trimming
Tail gate windscreen sealant
Tailgate inner trim board clips
Tail gate remote buzzer

set	\$	ma	15.00	✓
1	\$	ma	40.00	30sn
1	\$	ma	60.00	30sn
1	\$	sn	400.00	✓
set	\$	ma	80.00	✓
1	\$	sn	150.00	✓
1	\$	ma	60.00	40sn
set	\$	ma	60.00	✓
1	\$	sn	95.50	✓

Labour

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.
Remove & refix dashboard and internal wiring
Remove & replace front radar sensor & conduct distance safety setting
Remove & refix aircon condenser and refill aircon gas
Remove & refix radiator, top up coolant & conduct pressure test
Remove & refix tailgate windscreen glass
Remove & refix/replace rear bumper reverse sensor & conduct distance safety setting
Remove & refix/replace rear reverse camera & conduct distance safety setting
Remove & refix/replace rear exhaust system
Transfer of existing tailgate mechanism to new tailgate
Remove & refix/replace rear undercarriage work
To conduct wheel alignment
To conduct rear chassis alignment
Conduct water leak test for rear portion associated repair work
Wiring /bulb checking/focusing
To putty & spray paint accident damaged parts and adjacent panels

\$	1,800.00	✓
\$	sn 300.00	✓
\$	200.00	801
\$	120.00	1001
\$	90.00	501
\$	120.00	✓
\$	70.00	501
\$	70.00	401
\$	90.00	601
\$	90.00	601
\$	350.00	2001
\$	100.00	601
\$	250.00	✓
\$	40.00	201
\$	100.00	401
\$	2,000.00	✓
\$	34,754.93	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: