

3 MOTORWERKZ CONCEPT PTE LTD

25 KAKI BUKIT ROAD 4 #01-40 (JAY LIM 97972800)

Not Authorized
in
mech
23/9/24
2/6 6600
- take photo. Add. ref.

VEHICLE No : SJE 600Z

BYD NETT

1PC	TAILGATE	Body 20	3460	\$3,880.00	✓
1PC	TAILGATE INNER TRIM	SC		\$280.00	X
1PC	TAILGATE INNER LOCK	SC		\$180.00	X
1PC	TAILGATE WEATHERSTRIP	SC		\$166.00	X
1PC	REAR WINDSCREEN	11		\$1,230.00	X
1PC	REAR BUMPER	Dis		\$1,330.00	✓
1PC	REAR BUMPER SIDE LH	TM		\$178.00	✓
1PC	REAR BUMPER SIDE GARNISH N/S	cu7		\$90.00	✓
1PC	REAR BUMPER TOW COVER N/S	Che		\$28.00	✓
1PC	REAR BUMPER REFLECTOR N/S	SC		\$21.00	✓
1PC	REAR BUMPER LOWER SKIRTING	Torn		\$280.00	✓
1PC	REAR BUMPER PDC SENSOR N/S	SC		\$200.00	X
1PC	REAR BUMPER BEAM	Bent		\$650.00	✓
1PC	REAR END PANEL	W/Bent		\$1,082.00	✓
1PC	REAR END PANEL TOP GARNISH	11		\$280.00	X
1PC	REAR FENDER N/S	2		\$2,900.00	X
1PC	REAR FLOOR PANEL	11		\$2,590.00	X
1PC	TAILLAMP N/S	11		\$750.00	X
				\$16,115.00	
				LESS 10%	\$14,503.50

S.NETT

1SET	REAR BUMPER CLIPS	11	\$30.00	✓	S/N
1PC	REAR WINDSCREEN SEALANT	11	\$40.00	✓	S/N
1PC	REAR WINDSCREEN INNER SEAL	11	\$20.00	✓	S/N
1PC	REAR LICENCE PLATE	SC	\$40.00	✓	S/N

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR PDC SENSOR	\$80.00	30
TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00	120
TO TRANSFER TAILGATE MECHANISM	\$100.00	50
TO DISMANTLE & REFIX SEAT CUSHION, UPHOLSTERY	\$120.00	60
TO SPRAY RUST PROOFING	\$100.00	50
LABOUR FOR PANEL BEATING, REPLACED PARTS	\$1,200.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	800

TOTAL \$17,903.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-7139
102
6425.1
130
1730
828.1
212
6628