



CHARN'S CUSTOMCRAFT

Automotive Claim Repair, Correction Welding, Body Line Repairs,
Spray Painting, Mechanical Repairs And Customizing of Cars
BLOCK 1010, BUKIT MELAWATI JALAN 3, 401 005, SEREMBANG 700724
BLOCK 1009, BUKIT MELAWATI JALAN 3, 401 005, SEREMBANG 700723
TEL: 02717054, 02733304 FAX: 027300761 MAIL: charnscustomcraft.com.sg
Dun Reg No 25151300M GST Reg No M001616611

MS FIRST CAPITAL INSURANCE PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

ESTIMATE

CLAIM TYPE 3RD PARTY - MAIN
DATE OF ACCIDENT 10/09/2024
DATE 19/09/2024

VEHICLE NO.	MAKE/MODEL	CHASSIS NO.
SLW3701C	HONDA ODYSSEY 2.4 EX-S CVT	JHMRC1880JC201010 (2017)

SN	DESCRIPTION	QTY	RATE	TAX	AMOUNT
1	Rear Wheel Rim RHS <i>SLW</i> <i>Repair / Polish</i>		850.00	SR 9%	<i>Repair</i> 850.00
2	Discount 20%	1	-170.00	SR 9%	-170.00
3	Alignment	1	70.00	SR 9%	70.00
4	Remove necessary parts. Jacking, panel beating, repair and straighten rear bumper, rear fender RHS and rear door RHS.	1	300.00	SR 9%	300.00
5	Putty and respray rear bumper, rear fender RHS and rear door RHS.	1	800.00	SR 9%	<i>600</i> 800.00
SUBTOTAL					1,850.00
GST					166.50
TOTAL					S\$2,016.50

Note: The above is an estimate only. If other parts requested during the course of repair, we will inform you accordingly. All parts are subject to availability.

This is computer generated. No Signature is required.

Labour only - \$1058/-

Polish / Repair rim - 100.00

70.00

300.00

600.00

1070.00

80.00

Price

Hp 90010068

4 days

P/P

23/09/24

Rev after

24th