

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Email: pang_s_s_m@singnet.com.sg

ESTIMATE REPAIR

BIKE NO.: **FBM7572C**

DOA : **16/9/2024**

MAKE/MODEL : **HONDA CB400X**

S/No	DESCRIPTION	AMOUNT
1	HANDLE END	\$ <i>wt</i> 85.00
2	HANDLE BAR	\$ <i>bt</i> 185.00
3	R/H MIRROR	\$ <i>wt</i> 85.00
4	BRAKE LEVER	\$ <i>bro</i> 95.00
5	CRASH BAR	\$ <i>dd</i> 450.00
6	F WHEEL RIM	\$ <i>bt</i> 620.00
7	F BRAKE DISC	\$ <i>bt</i> 320.00
8	MUFFLER ASSEMBLY	\$ <i>dd</i> 680.00
9	MUFFLER GUARD	\$ <i>wt</i> 120.00
10	UNDER BRACKET	\$ <i>bt</i> 385.00
11	STEERING CON (1 SET)	\$ <i>nel</i> 165.00
12	FORK INNER TUBE (x 2)	\$ <i>bt</i> 560.00
13	FORK OIL SEAL (x 2)	\$ <i>nel</i> 150.00
14	RADIATOR ASSEMBLY	\$ <i>bt</i> 480.00
15	COOLANT	\$ <i>nel</i> 45.00
16	WINDSHIELD	\$ <i>wt</i> 285.00
17	GEAR PEDAL	\$ <i>bt</i> 185.00
18	REAR BOX	\$ <i>wt</i> 285.00
19	FORK OIL (x 2)	\$ <i>nel</i> 100.00
20	F WHEEL BEARING (x 2)	\$ <i>nel</i> 80.00
21	MUFFLER JOIN GASKET	\$ <i>nel</i> 40.00
22	LABOUR	\$ <i>300</i> 500.00
Total :		\$ 5,900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taujiah 97495749 03days
26/9/24 2530pm
Resurvey after repair
Taujiah @ lkk auto. com.