

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Quotation
 DATE : 20.09.2024
 VEH NO : SJX7507P
 MODEL : Honda Freed
 D O A : 19.09.2024
 YR REF : SMZ7870T

Yan.

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJX7507P (HONDA FREED)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Dehd</i>	1	988.20 ✓
2	Front Bumper Side Holder - LH & RH <i>new</i>	2	60.20 +
3	Front Bumper Reinforcement <i>Dented</i>	1	351.60 ✓
4	Front Grille <i>Crackd</i>	1	312.90 ✓
5	Front Grille Top Moulding <i>Crackd</i>	1	100.20 ✓
6	Front Grille Centre Moulding <i>new</i>	2	110.40 +
7	Front Grille Lower Moulding	1	108.20 +
8	Front Grille Logo <i>Missing</i>	1	40.90 ✓
9	Headlamp <i>Crackd</i>	2	1,737.40 ✓
10	Headlamp Top Panel <i>Buckled</i>	2	190.80 ✓
11	Bonnet <i>Dented</i>	1	986.40 ✓
12	Bonnet Lock <i>Jammed</i>	1	95.10 ✓
13	Bonnet Hinge <i>Bent</i>	2	148.20 ✓
14	Front Support Panel <i>Buckled</i>	1	663.40 ✓
15	Air Con Condenser <i>Dented</i>	1	936.60 ✓
16	Air Con Condenser Mounting <i>new</i>	2	50.00 ✓
17	Air Con Fan Blade <i>new</i>	1	46.50 +
18	Air Con Fan Cowling <i>Crackd</i>	1	100.90 ✓
19	Air Con Fan Motor <i>new</i>	1	233.60 +
20	Radiator <i>Dented</i>	1	1,355.80 ✓
21	Radiator Top Bracket <i>new</i>	2	21.00 +
22	Radiator Fan Cowling <i>Crackd</i>	1	98.90 ✓
23	Radiator Fan Motor <i>new</i>	1	308.90 +
24	Radiator Fan Blade <i>new</i>	1	54.80 +
			<hr/>
			9,100.90
			(1,820.18)
			<hr/>
			\$ 7,280.72

8157.30

6525.84

Less 20%

RE : ESTIMATE FOR ACCIDENT REPAIR SJX7507P (HONDA FREED)

S/NETT ITEMS

1	Front Number Plate	<i>could add</i>	1	30.00	✓
2	Front Number Plate Holder	<i>add</i>	1	30.00	✓
3	Front Bumper Clips	<i>for</i>	1 set	30.00	✓
4	Front Grille Clips	<i>160</i>	1 set	20.00	✓
5	Coolant	<i>new</i>	1	50.00	✓
				\$ 160.00	

Total Parts \$ 7,440.72

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts		\$ 1,200.00	<i>800</i>
2	To putty & spray up paint works		\$ 1,000.00	<i>700.</i>
3	To check wiring		\$ 50.00	<i>30</i>
4	To remove condenser & top-up gas	<i>1710</i>	\$ 120.00	<i>60</i>
5	To remove radiator & top-up coolant		\$ 120.00	<i>60</i>
6	To apply tuff coat		\$ 150.00	<i>60</i>
			\$ 2,640.00	
Grand Total			\$ 10,080.72	

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 839584
h/s: GTR
06 Days