

REF:

C/AIG 24060173/Aq3

ASSIGNMENT

FRONT _____ Date: _____
 Estin ~~Estimate~~ _____
 OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV
 To in ~~Vehicle~~ No: _____
 at ~~Work~~ / ~~Shop~~ / ~~Home~~ / ~~Other~~ _____
 of _____
 Insured: _____
 Policy No _____
 Claims No _____
 Sum Insured _____ Excess: 550
 (Client's Record)
 Make of Vch _____
 (Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKG6447M Yr Regn: 2022, August.
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.D. 1984

Colour Black A/C: Insured / Std / NI / NA

Sp. Reading 20624 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F49MA077982Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/50 R17R: 225/50 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 24/06/24.

Survey held at

PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 ALG

COE Expiry

Finalised with Allan final fig @ 6079.60, 3 days
(Nett @ 17950.40, 75%)

Estimate given during : Yes C ✓

1st Survey : No C ✓

MV: 180KPV: 118.7KNett: 61.3K

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$

Survey Fee:

Transportation:

S + R.S. \$1

Photos

Others

Report Format:

Nett R-00

Report Form: F.R.P. / F.R.P. / F.R.P.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0484/2024/KS
DATE : 21-Jun-24
WIP : 20063

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/6/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR GANDAVALLI RAMANIAH PRASANNA
ADDRESS : BLOCK 669 JALAN DAMAI
#12-57
SINGAPORE 410669
TELEPHONE : HP +65 91087935
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220098855-01
VEHICLE NO : **SKG 6647 M**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 29/8/2022
ENGINE NO : DEM 03319
CHASSIS NO : WAUZZZF49MA077992
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Jun-24
PLACE OF ACCIDENT : GELANG PATAH, JOHOR, MALAYSIA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SKG 6447 M.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	1,800.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,322.00	

Car in 8/11 wip 20063

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1163
EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ATG - Adrian
- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 6447 M

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
SK - 1	FRONT BUMPER <i>rehd</i>	1	\$ 2,670.00	✓ 2136
2	FRONT BUMPER FIXINGS PARTS <i>me n</i>	1	\$ 420.00	+
3	FRONT BUMPER SECURING STRIP <i>me n</i>	2	\$ 90.00	+
4	FRONT BUMPER GRILLE - CENTER <i>me n</i>	1	\$ 245.00	+
5	FRONT BUMPER CLOSING ELEMENT - CENTER <i>me n</i>	1	\$ 329.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>me n</i>	2	\$ 178.00	+
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>me n</i>	1	\$ 329.00	✓ 2136
8	FRONT BUMPER AIR GUIDE - LH / RH <i>me n</i>	2	\$ 338.00	+
9	FRONT BUMPER AIR GUIDE GRILLE TRIM - LH / RH <i>me n</i>	2	\$ 120.00	+
10	RADIATOR GRILLE <i>me n</i>	1	\$ 1,949.00	- 1559.00
11	FRONT PARKING AID SENSOR	2	\$ 572.00	+
12	FRONT PARKING AID SENSOR SEAL RING	4	\$ 11.00	+
13	FRONT LOCK CARRIER TOP BRACKET	1	\$ 173.00	+
14	FRONT FOAM FILLER PIECE <i>me n</i>	1	\$ 237.00	✓ 189.60
15	FRONT REINFORCEMENT BEAM <i>me n</i>	1	\$ 1,033.00	+
16	FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>me n</i>	2	\$ 570.00	+
17	LOCK CARRIER TOP BRACKET SUPPORT - LH / RH <i>me n</i>	1	\$ 74.00	+
18	OUTSIDE TEMP SENSOR BRACKET <i>me n</i>	1	\$ 30.00	+
19	LED HEADLIGHT - LH <i>me n</i>	1	\$ 9,204.00	+
20	LED HEADLIGHT SPACER <i>me n</i>	3	\$ 150.00	+
SUB TOTAL SPARE PARTS		:	\$ 18,720.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Desurveyed
Adrian
R.S.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKG 6447 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER - LH	1	\$ 252.00	+
22	LIFT CYLINDER BRACKET	1	\$ 8.00	+
23	LIFT CYLINDER HOSE	1	\$ 118.00	+
24	FRONT NO PLATE	S/N	\$ 60.00	✓
25	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 19,658.00	
TOTAL LABOUR CHARGES		:	\$ 4,322.00	
GRAND TOTAL		:	\$ 23,980.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *24/06/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Are Authorized, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT