

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401903

INV Date : 18-12-2024

Reference CD/LPC24090368/Tpa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. FBU 6002X
Insured Veh. SMU 4113S
Claim No. 23/24/24/VP05/029875
Policy No. Z23VP05034590
Accident Date 13/09/2024
Inspection Date 20/09/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24090368/Tpa3q2
300 BEACH ROAD	Date:	18/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SMU 4113S	Veh. Inspected	FBU 6002X
Policy No.	Z23VP05034590	Coverage	0
Claim No.	23/24/24/VP05/029875	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	20/09/2024

2. Vehicle Details

Make & Model	HONDA ADV 160 ABS CVT	C.C	157
Engine No.	KFB2E1001865	Year of Reg.	10/01/2023
Chassis No.	MH1KFB21XNK001879	Colour	RED
Odometer	0 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110/80 R14	MAXXIS	5
L/H Front Tyre			
R/H Rear Tyre	130/70 R13	MAXXIS	5
L/H Rear Tyre			-

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/09/2024	Inspection Date	20/09/2024
Survey held at	ERZAT LEE MOTOR TRADING PTE LTD 25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBU 6002X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT TYRES	NOT NECESSARY	\$120.00	\$0.00
1	FRONT RIM	CUT	\$350.00	\$300.00
1	FRONT BRAKE DISC	NOT NECESSARY	\$130.00	\$0.00
1	FRONT FANDER	CRACKED	\$90.00	\$90.00
1	T FORK	NOT NECESSARY	\$120.00	\$0.00
1	STEERING CONE	NECESSARY	\$190.00	\$50.00
1	FLOOR STEP LEFT	NOT NECESSARY	\$100.00	\$0.00
1	FLOOR STEP RIGHT	DEFORMED	\$100.00	\$100.00
1	FRONT LOWER COVER	CUT	\$110.00	\$110.00
1	FLOOR LEFT SIDE COVER	DEFORMED	\$85.00	\$85.00
1	FLOOR RIGHT SIDE COVER	DEFORMED	\$85.00	\$85.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$82.00)
			\$1,480.00	\$738.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FORK LEFT (SN) }	DAMAGED	\$180.00	\$150.00
1	FORK RIGHT (SN) }	DAMAGED	\$180.00	\$0.00
			\$360.00	\$150.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR		\$600.00	\$300.00
			\$600.00	\$300.00

GRAND TOTAL		\$2,440.00	\$1,188.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$950.00
Report Ref No: CD/LPC24090368/Tpa3q2			

MARKET VALUE: \$15,000.00(EST) LESS LTA REBATE: \$9,697.00(EST) = NETT VALUE :\$5,303.00(EST)

MTH

MOHAMAD TAUFIKH



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 16 of 16)

PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 7)

PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X




PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X



PHOTOGRAPHS FOR VEHICLE NO. : FBU 6002X

