

# One Line Motorworks Trading

11, Tuas Bay Close #06-03 West Star, Singapore 636996

Tel: 62622106

Company Reg No: 53375959E

Email: [tricia.onelinemotorworks@gmail.com](mailto:tricia.onelinemotorworks@gmail.com)

23<sup>RD</sup> February 2024

$1512.00$   
 $103.50$   
 $1260.00$   


---

 $2875.50$   
 $209$   
 $2300.40$

BY HAND

## THIRD-PARTY CLAIM YP8476C- REPAIR ESTIMATE FOR PC8684T

TRAFFIC ACCIDENT ON 30/01/2024, TRAFFIC ACCIDENT Near AYE, Jurong Hill Flyover, Singapore

To whomever it concerns,  
We append below our repair estimate for PC8684T

### Repair Estimate

#### Parts required:

- |  |      |    |              |
|--|------|----|--------------|
| 1. Rear Engine Compartment Door <i>HT repair</i> | 1680 | \$ | 3500.00 XR   |
| 2. Gas Spring x 2pcs <i>X SUC</i>                | 10%  | \$ | 600.00 X     |
| 3. Bumper Reinforcement <i>? X SUC</i>           |      | \$ | 2000.00 X    |
| 4. Compartment Lock <i>X SUC</i>                 | 1512 | \$ | 500.00 X     |
| 5. Rear Bumper <i>com</i>                        |      | \$ | 2000.00 1680 |
| 6. Door Sensor <i>X SUC</i>                      |      | \$ | 800.00 X     |

#### Nett Items:

- |                                    |        |    |            |
|------------------------------------|--------|----|------------|
| 1. 60km/h sticker <i>me</i>        | 115    | \$ | 100.00 15  |
| 2. Paintwork stencil <i>to XAN</i> | 10%    | \$ | 800.00 X   |
| 3. "KING LONG" logo <i>me</i>      | 103.50 | \$ | 500.00 100 |
| 4. Sealant <i>me XAN</i>           |        | \$ | 300.00 X   |


#### Labour charges:

- |   |                |      |    |                |
|---|----------------|------|----|----------------|
| 1. To replace rear engine compartment door  | \$350 x 2 days |      | \$ | 700.00 280     |
| 2. To replace rear bumper & reinforcement   | \$350 x 2 days | 1260 | \$ | 700.00 280     |
| 3. To replace gas spring & compartment lock | \$350 x 1 day  |      | \$ | 350.00 XAN     |
| 4. To hire stencil artist to apply stencil  | \$800 x 1 day  |      | \$ | 800.00 280 XAN |
| 5. To spray paint affected areas            | \$800/panel    |      | \$ | 2400.00 700    |

**\$ 16,050.00**

#### Total repair costs:

This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.



Neo Say Pheng  
(HP: 9797 1868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Rasul*  
*HP 900 10 68*  
*4 days*  
*4/5*  
*24/09/24*  
*Resy after repair*