

# One Line Motorworks Trading

11, Tuas Bay Close #06-03 West Star, Singapore 636996

Tel: 62622106

Company Reg No: 53375959E

Email: [tricia.onelinemotorworks@gmail.com](mailto:tricia.onelinemotorworks@gmail.com)

23<sup>RD</sup> February 2024

BY HAND

## THIRD-PARTY CLAIM YP8476C- REPAIR ESTIMATE FOR PC8684T

TRAFFIC ACCIDENT ON 30/01/2024, TRAFFIC ACCIDENT Near AYE, Jurong Hill Flyover, Singapore

To whomever it concerns,  
We append below our repair estimate for PC8684T

### Repair Estimate

#### Parts required:

1. Rear Engine Compartment Door	H ✓ X Repair (Minor damage, old model)	\$	<del>3500.00</del>
2. Gas Spring x 2pcs	X	\$	600.00
3. Bumper Reinforcement	?	\$	2000.00
4. Compartment Lock	X	\$	500.00
5. Rear Bumper	can ✓ ✓	\$	2000.00 (Please check price)
6. Door Sensor	X	\$	800.00

#### Nett Items:

1. 60km/h sticker	✓ ✓ ✓ \$15	\$	100.00
2. Paintwork stencil	✓ X	\$	<del>800.00</del>
3. "KING LONG" logo	✓ ✓ \$100	\$	500.00
4. Sealant	✓ X	\$	<del>300.00</del>

#### Labour charges:

1. To <del>replace</del> <sup>Repair</sup> rear engine compartment door	\$350 x 2 days	\$	<del>700.00</del> 280 ✓
2. To replace rear bumper & reinforcement	\$350 x 2 days	\$	<del>700.00</del> 280 ✓
3. To replace gas spring & compartment lock	\$350 x 1 day	\$	350.00 X
4. To hire stencil artist to apply stencil	\$800 x 1 day	\$	<del>800.00</del> 280 X
5. To spray paint affected areas	\$800/panel	\$	<del>2400.00</del> 700 ✓

#### Total repair costs:

\$ 16,050.00

This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.



Neo Say Pheng  
(HP: 9797 1868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
HP 90010068  
4 days  
4/3  
24/09/24  
Resy after repair