

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

merang

23/9/24

2/5 \$1500

the phr. Atk. my

23 September 2024

REG NO.: SKK 4410 K
MAKE/MODEL : HONDA ODYSSEY

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet 17	\$ 860.60 X
1	Front headlamp 17	\$ 1,075.60 X
1	Front headlamp lower bracket 17	\$ 95.00 X
1	Radiator grille base cur/cru	\$ 302.40 X
2	Radiator grille chrome top su	\$ 77.20
1	Radiator grille chrome lower chrome sen	\$ 115.20 275.40 ✓
1	Radiator grille logo 17	\$ 414.80 X
1	Front bumper cur/Toin	\$ 779.20 ✓
1	Front bumper fog lamp 17	\$ 740.90 X
1	Front bumper fog lamp grille 17	\$ 42.50 X
1	Front bumper lower grille cur/Toin	\$ 646.50 ✓
1	Front bumper reinforcement 17	\$ 230.20 X
2	Front bumper side retainers 17	\$ 77.00 X
1	Front bumper PDC sensor su	\$ 280.00 X
1	Front fender 17	\$ 529.50 X
1	Front support panel 17	\$ 748.50 X
		\$ 7,175.30
	Less 20%	\$ 1,435.06
		\$ 5,740.24

SPECIAL NETT ITEMS

1	Front bumper clip (1 set) all	\$ 80.00 30 s/d
1	Front number plate with holder su	\$ 50.00 X
		\$ 130.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove and refit front sensor.	\$ 150.00 30
3	To apply undercoating.	\$ 17 200.00 X
4	Panel beating.	\$ 1,800.00 250
5	To re-spray painting on the affected areas.	\$ 1,600.00 300
		\$ 3,830.00

GRAND TOTAL :

\$ 9,700.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1618-1
202
129448
30
600
1924.48
21
1539